

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401993789
Date Received:
04/02/2019

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tesla Dougherty

970-304-5245

tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682404331

Inspection Date: 12/24/2018

FIR Submit Date: 12/27/2018

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 330539

Location Name: SLW GREEN STATE-65N63W Number: 18NWSE County: _____

Qtrqr: NWSE Sec: 18 Twp: 5N Range: 63W Meridian: 6

Latitude: 40.396956 Longitude: -104.476915

FACILITY - API Number: 05-123-00 Facility ID: 330539

Facility Name: SLW GREEN STATE-65N63W Number: 18NWSE

Qtrqr: NWSE Sec: 18 Twp: 5N Range: 63W Meridian: 6

Latitude: 40.396956 Longitude: -104.476915

CORRECTIVE ACTIONS:

1 ☒ CA# 121363

Corrective Action: Comply with Rule 603.f. to control and manage weedy, annual vegetation to prevent weed waste and prevent spread of dispersing seeds onto adjacent lands.

Date: 01/10/2019

Response: CA COMPLETED

Date of Completion: 03/12/2019

Operator Comment: Weed mitigation (mowing) successfully implemented

COGCC Decision: Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an

COGCC Representative: acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

2 ☒ CA# 121364

Corrective Action: Comply with Rule 1003 to properly stabilize production areas and interim areas.

Date: 01/24/2019

Response: CA COMPLETED

Date of Completion: 03/22/2019

Operator Comment: Multiple stabilization control measures have been implanted. Control measures include: re-grading/contouring, seeding, and crimped mulch installation.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: _____

Title: EHS Specialist

Date: 4/2/2019 3:46:48 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401993789	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files