

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402016875
Date Received:
04/22/2019

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10261
Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLC
Address: 730 17TH ST STE 500
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Mark Brown	303-893-2503	mbrown@bayswater.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 682404758
Inspection Date: 04/02/2019 FIR Submit Date: 04/03/2019 FIR Status: _____

Inspected Operator Information:

Company Name: BAYSWATER EXPLORATION & PRODUCTION LLC Company Number: 10261
Address: 730 17TH ST STE 500
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 455456

Location Name: EAST AULT Number: 18-C PAD County: _____
Qtrqtr: NWNE Sec: 18 Twp: 7N Range: 65W Meridian: 6
Latitude: 40.581680 Longitude: -104.704933

FACILITY - API Number: 05-123-00 Facility ID: 455456

Facility Name: EAST AULT Number: 18-C PAD
Qtrqtr: NWNE Sec: 18 Twp: 7N Range: 65W Meridian: 6
Latitude: 40.581680 Longitude: -104.704933

CORRECTIVE ACTIONS:

1 ☒ CA# 123807

Corrective Action: Comply with Rule 1002.c. Corrective action date is being back dated to the previous Field Inspection Report.

Date: 03/12/2019

Response: CA COMPLETED Date of Completion: 04/05/2019

Operator Comment: The South side of the topsoil was tracked to adequately stabilize on 4/5/2019.

COGCC Decision: Approved via an AMI

Appears the Operator has stabilized the topsoil stockpile per the corrective action. Operator shall monitor BMP.

COGCC
Representative:

equipment tracking is only a temporary stabilization BMP and may require additional maintenance and additional BMPs.

Operator shall ensure compliance with other sections of Rule 1002c, like, preventing weed establishment and to maintain soil microbial activity.

OPERATOR COMMENT AND SUBMITTAL

Comment: In addition to the topsoil pile being stabilized, the perimeter of the disturbed area is planned for silt fence installation on 4/23/2019.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mark Brown

Signed: _____

Title: Operations Manager

Date: 4/22/2019 3:31:59 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402016875	FIR RESOLUTION SUBMITTED
402016958	Tracking of Topsoil Pile

Total Attach: 2 Files