

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/02/2019

Submitted Date:

05/02/2019

Document Number:

679703950

FIELD INSPECTION FORM

Loc ID 316416 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, Foundation		regulatory@foundationenergy.com	Regulatory

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273520	WELL	PR	01/01/2019	GW	103-10478	COLUMBINE SP FED 1C-23-4-104	PR

General Comment:

[COGCC Inspection Report Summary.](#)

On 5/2/2019 at approximately 16:30, inspector Rick Moran, attempted to conduct a follow up inspection at Foundation Energy Management's well Columbine Springs Federal 1C-23-4-104 in Rio Blanco county. The inspector did not have the lock code for the 3rd gate across the lease road.

The corrective actions of an unmarked deadmand & tank label identified in FIR document 679701986 were responded to in FIRR document 401879257.

This is a summary of inspection report 679703950.

Inspected Facilities

Facility ID: 273520 Type: WELL API Number: 103-10478 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well with the last recorded production in 2-2019.](#)

Corrective Action:

Date: