

APACHE CANYON 19-16 API# 05-071-08888 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: MAY 02, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401843



PHOTO 1: THE COLLECTION OF IMPACTED SOIL THAT WAS PLACED NEXT TO THE SEPARATOR HOUSE WAS REMOVED FROM THE LOCATION.

APACHE CANYON 19-16 API# 05-071-08888 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: MAY 02, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401843



PHOTO 2: THE IMPACTED SOIL NEXT TO THE ENGINE SKID WAS REMOVED FROM THE LOCATION.

APACHE CANYON 19-16 API# 05-071-08888 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: MAY 02, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401843



PHOTO 3: THE IMPACTED SOIL NEXT TO THE ENGINE SKID WAS REMOVED FROM THE LOCATION.