

GOLDEN EAGLE 17-14 API# 05-071-08051 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – DATE 04/12/19 AND DATE: MAY 07, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401825



PHOTO 1: THE IMPACTED SOIL AROUND THE WELL HEAD WAS CLEANED UP AND REMOVED FROM THE LOCATION. ALL VALVES AND FITTINGS WERE SECURELY FASTENED ON 04/12/19 TO STOP THE LEAKING PACKINGS.

GOLDEN EAGLE 17-14 API# 05-071-08051 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – DATE: MAY 07, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401825



PHOTO 2: (PHOTO WAS TAKEN DURING RAIN SHOWERS) THE IMPACTED SOIL NEXT TO THE ENGINE SKID WAS REMOVED FROM THE LOCATION.