

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2019

Submitted Date:

05/13/2019

Document Number:

688402161

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
456747 _____ Silver, Randy _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL & GAS INC

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
Carlisle, J	970-534-6006	COGCCInspections@extracti onog.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456752	WELL	DG	03/24/2019		014-20772	Interchange B N35-20-5C	DG

General Comment:

Inspected Facilities

Facility ID: 456752 Type: WELL API Number: 014-20772 Status: DG Insp. Status: DG

Complaint

Comment: **Field Inspector Assigned: Randy Silver**
 Complaint Received
 Date: 05-12-2019
 Complaint Contacted:
 Date: 05-13-2019 Time: 12:15PM via phone
 Facility ID #: 456747
 Inspection Document # 688402156

 Nature of Complaint: odor
 Field Inspector Actions:
 On 05-13-2019, I was contacted by COGCC staff about a complaint received by the COGCC in reference to Odor. The complainant stated the issues were occurring at 152nd ,144th and Huron street, from the Interchange A&B pad.
 On 05-13-2019, I attempted to make contact with the complaint who indicated on 5-11-19 at approx.... 2:19PM she smelled oil or petroleum products at 152nd and Huron. At 2:25 on the same day, she smelled benzene or something similar at 144th and Huron. I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I talked with Extraction drilling supervisor he stated at time of complaint they were drilling and no unusual activity was taking place. We also spoke about adjusting odorant being used in drill cuttings. At time of inspection, I did not smell any unusual odors. I spoke with Broomfield inspectors and they are aware of complaint and have responded to it.
 See inspection document #688402156 per my inspection.
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
See Doc#688402156 for complete inspection.	silverr	05/13/2019