



Report Date <u>05/14/2019</u>
Document Number <u>402039227</u>

**OPERATOR'S MONTHLY REPORT OF OPERATIONS
ERROR REPORT**

OPERATOR INFORMATION

OGCC Operator Number: <u>10560</u>	Contact Name and Telephone:
Name of Operator: <u>WEST TEXAS OPERATING CO LLC DBA XTREME ENERGYCO</u>	Name: <u>MIKE GRAY</u>
Address: <u>PO BOX 2326</u>	Phone: <u>(361) 5701600</u> Fax: <u>(361) 5706097</u>
City: <u>VICTORIA</u> State: <u>TX</u> Zip: <u>77902</u>	Email: <u>mgray@xeogc.com</u>

Summary Totals:

Total Error(s): 0 Total Modified(s): 6 Total Deleted(s): 0

Total 0 Error(s)

Report Month/Year: /

#

Comment:

Total 6 Modified(s)

Report Month/Year: 03/2019

#1	009-06569-00	ALLEY 2-17	RDCV	PR	[MODIFIED] MODIFIED	Comment: INCORRECT LOCATION - TOWNSHIP CORRECTED TO 33S
#2	009-06569-00	ALLEY 2-17	TOPK	SI	[MODIFIED] MODIFIED	Comment: INCORRECT LOCATION - TOWNSHIP CORRECTED TO 33S
#3	009-06569-00	ALLEY 2-17	WBNS	SI	[MODIFIED] MODIFIED	Comment: INCORRECT LOCATION - TOWNSHIP CORRECTED TO 33S
#13	009-05161-00	SCHWEITZER-	TOPK	SI	[MODIFIED] MODIFIED	Comment: INCORRECT LOCATION - QQ CORRECTED TO SWNE, TOWNSHIP CORRECTED TO 32S, RANGE CORRECTED TO 41W
#14	009-05161-00	SCHWEITZER-	LNSNG	SI	[MODIFIED] MODIFIED	Comment: INCORRECT LOCATION - QQ CORRECTED TO SWNE, TOWNSHIP CORRECTED TO 32S, RANGE CORRECTED TO 41W
#15	009-05148-00	WATKINS FRANK S	TOPK	PR	[MODIFIED] MODIFIED	Comment: INCORRECT LOCATION - RANGE CORRECTED TO 41W

Total 0 Deleted(s)

Report Month/Year: /

#

[]

Comment: