

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/09/2019

Submitted Date:

05/10/2019

Document Number:

694500101

FIELD INSPECTION FORM

Loc ID 458790	Inspector Name: NEIDEL, KRIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10598 Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC Address: 123 ROBERT S KERR AVE City: OKLAHOMA CITY State: OK Zip: 73102				Findings: 3 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
James, General		sandridgeenvironmental@sandridgeenergy.com	
Waldron, Emily		emily.waldron@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Kubeczko, Dave		dave.kubeczko@state.co.us	
Noto, John		john.noto@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
460343	WELL	DG	03/13/2019		057-06612	PRU 0880 2-29H17	EI
460345	WELL	DG	03/15/2019		057-06614	PRU 0880 6-29H17	EI
462052	WELL	DG	03/11/2019		057-06615	Patriot 0880 12-32H5	EI
462053	WELL	DG	03/03/2019		057-06616	Patriot 0880 15-32H5	EI
462054	WELL	DG	03/06/2019		057-06617	Patriot 0880 14-32H5	EI
462055	WELL	DG	03/09/2019		057-06618	Patriot 0880 13-32H5	EI

General Comment:

On 5/9/2019 COGCC Environmental; Staff, Kris Neidel inspected location ID # 458790. The weather was 37 degrees with light flurries the ground surface was dry. Environmental Staff observed the cuttings management area. Crews were moving cuttings from the rig shaker bin to storage bins lined up out away from the rig to the north edge of location. Cuttings are being tracked out of the cuttings management area when loading trucks. The cuttings management is completely covered in cuttings material. No trucks were being loaded at the time of inspection. All cuttings should be managed and stored as E&P, cuttings should be, "stored in a way that prevents threatened or actual significant adverse environmental impacts...to soil..." (COGCC rules 907.a(1)). Crews were installing a French Drain, off location, to the South and east of location. The drain was being installed along the full length of the pad to the south and east, approximately 12 feet deep. It was reported that the drain is intended to discharge to the north east of the pad, (down surface grade). Sandridge should consult with COGCC OGLA staff; Dave Kubeczko and John Noto to determine if an amended 2A is required for this activity. Sandridge should acquire any permits or notices to Division of Water Resources or CDPHE as required for this activity.

Location Construction

Location ID: 458790 CDP: _____

Comment: Crews were installing a French Drain, off location, to the South and east of location. The drain was being installed along the full length of the pad to the south and east, approximately 12 feet deep. It was reported that the drain is intended to discharge to the north east of the pad, (down surface grade)

Corrective Action: Sandridge should consult with COGCC OGLA staff; Dave Kubeczko and John Noto to determine if an amended 2A is required for this activity

Date: 05/17/2019

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: <u>460343</u>	Type: <u>WELL</u>	API Number: <u>057-06612</u>	Status: <u>DG</u>	Insp. Status: <u>EI</u>
Facility ID: <u>460345</u>	Type: <u>WELL</u>	API Number: <u>057-06614</u>	Status: <u>DG</u>	Insp. Status: <u>EI</u>
Facility ID: <u>462052</u>	Type: <u>WELL</u>	API Number: <u>057-06615</u>	Status: <u>DG</u>	Insp. Status: <u>EI</u>
Facility ID: <u>462053</u>	Type: <u>WELL</u>	API Number: <u>057-06616</u>	Status: <u>DG</u>	Insp. Status: <u>EI</u>
Facility ID: <u>462054</u>	Type: <u>WELL</u>	API Number: <u>057-06617</u>	Status: <u>DG</u>	Insp. Status: <u>EI</u>
Facility ID: <u>462055</u>	Type: <u>WELL</u>	API Number: <u>057-06618</u>	Status: <u>DG</u>	Insp. Status: <u>EI</u>

Environmental**Spills/Releases:**Type of Spill: DRILLING CUTTINGS

Estimated Spill Volume: _____

Comment: Cuttings are being tracked out of the cuttings management area when loading trucks. The cuttings management is completely covered in cuttings material.

Corrective Action: All cuttings should be managed and stored as E&P, cuttings should be, "stored in a way that prevents threatened or actual significant adverse environmental impacts...to soil..." (COGCC rules 907.a(1)).

Date: 05/14/2019Reportable: NO

GPS: Lat _____

Long _____

Proximity to Surface Water: 296

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402040832	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4821062
694500102	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4821055