

Columbine Springs Federal 10C-12-4-104

API: 05-103-10466

Inspection: 679704081



Photo 1. Location looking southwest.

Columbine Springs Federal 10C-12-4-104

API: 05-103-10466

Inspection: 679704081



Photo 2. Stormwater channeling across west edge of location and road.



Photo 3. Stormwater breached on north edge of location.

Columbine Springs Federal 10C-12-4-104

API: 05-103-10466

Inspection: 679704081



Photo 4. Stormwater entering under gas meter building.

Photo 5. Stormwater exiting under gas meter building.