

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/17/2019

Submitted Date:

05/19/2019

Document Number:

688402195

**FIELD INSPECTION FORM**

Loc ID 456747 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10459  
Name of Operator: EXTRACTION OIL & GAS INC  
Address: 370 17TH STREET SUITE 5300  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Carlisle, J	970-534-6006	COGCCInspections@extracti onog.com	<a href="#">ALL INSPECTIONS</a>
Adamczyk, Megan		megan.adamczyk@state.co.u s	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456757	WELL	DG	03/25/2019		014-20777	Interchange B N35-20-6N	DG

**General Comment:**

**Inspected Facilities**

Facility ID: 456757 Type: WELL API Number: 014-20777 Status: DG Insp. Status: DG

**Complaint**

Comment: **Complaint Received**  
 Date: 05-14-2019  
**Complaint Contacted:**  
 Date: Time: No contact  
 Facility ID #: 456747  
 Inspection Document # 688402192

Nature of Complaint: odor  
 Field Inspector Actions:  
 On 05-15-2019, I was contacted by COGCC staff about a complaint received by the COGCC in reference to Odor. The complainant stated the issues were occurring outside of her home, from the Interchange A&B pad.  
 On 05-17-2019, I attempted to make contact with the complaint who indicated on her complaint form that on 5-14-19 she experienced a strong fleeting toxic oil smell out of the east at her house. At time of inspection on 05-17-19 at approximately 12:30PM, I did not smell any unusual odors. I drove around complainant's neighborhood and Interchange B drilling pad were I performed a site inspection of the drilling operations. I spoke with Broomfield inspectors and they are aware of complaint.  
 See inspection document #688402192 per my inspection.  
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
See Doc# 688402192 for full inspection.	silverr	05/19/2019