

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2019

Submitted Date:

05/15/2019

Document Number:

679704070

**FIELD INSPECTION FORM**

Loc ID 314785 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: 6301 DEAUVILLE BLVD  
City: MIDLAND State: TX Zip: 79706

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Peterson, Diane	970-675-3842	dlpe@chevron.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229570	WELL	PR	08/31/1969	OW	103-07227	F V LARSON B-22X	PR

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 5/15/2019 at approximately 15:30, inspector Rick Moran, conducted a routine inspection at Chevron's well FV Larson B 22X in Rio Blanco county.

During this inspection the following compliance issues were observed:  
1) Broken deadman marker.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704070.

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-675-3700		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

				corrective date
Type: Submersible Pump	# 1			
Comment:				
Corrective Action:		Date:		
Type: Deadman # & Marked	# 3			
Comment:	One unmarked deadman.			
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:		06/05/2019

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 229570 Type: WELL API Number: 103-07227 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well on subpump.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402045900	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4824514">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4824514</a>
679704071	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4824470">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4824470</a>