

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402051887
Date Received:
05/22/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>-</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Beebe, Sabre</u>		<u>sabre.beebe@bpx.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900195
Inspection Date: 04/09/2019 FIR Submit Date: 04/18/2019 FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325074

Location Name: SOUTHERN UTE 32-8-N32N8W Number: 1NWNE County: LA PLATA
Qtrqr: NWNE Sec: 1 Twp: 32N Range: 8W Meridian: N
Latitude: 37.050676 Longitude: -107.664633

FACILITY - API Number: 05-067-00 Facility ID: 213931

Facility Name: SOUTHERN UTE 32-8 Number: 1-1
Qtrqr: NWNE Sec: 1 Twp: 32N Range: 8W Meridian: N
Latitude: 37.050676 Longitude: -107.664633

CORRECTIVE ACTIONS:

1 CA# 124384

Corrective Action: Reclaim areas around the plugged well, no longer needed for production operations. Date: 05/18/2019

Response: CA COMPLETED Date of Completion: 05/08/2019

Operator Comment: Area around plugged well on same location with active Southern Ute 32-8 1-7 well has been disced, seeded, mulched and crimped to establish vegetation in this area. Full reclamation not possible at this time due to on going production of active well on pad.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 124385

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area. Stormwater controls need to be selected, sized, and installed using good engineering practices. Successful revegetation of areas not needed for production will help stabilize the project area.

Date: 05/18/2019

Response: CA COMPLETED

Date of Completion: 05/08/2019

Operator Comment: Reduction of pad size with seeding, mulching and crimping have been performed to establish vegetation in areas not utilized by active well for on going operations.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: all corrective actions complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 5/22/2019 7:37:31 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402051889	Compliance follow up form
-----------	---------------------------

Total Attach: 1 Files