

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402054232

Date Received:

05/23/2019

FIR RESOLUTION FORM

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10548

Name of Operator: HRM RESOURCES II LLC

Address: 410 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Ferrin, Jeremy

richard_cottle@pogresources.com

jeremy.ferrin@state.co.us

dnr_cogccenforcement@state.co.us

tpape@hrmres.com

lrhutson@hrmres.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682504828

Inspection Date: 04/25/2019

FIR Submit Date: 05/01/2019

FIR Status: _____

Inspected Operator Information:

Company Name: HRM RESOURCES II LLC

Company Number: 10548

Address: 410 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 313925

Location Name: ALISSA-66N60W Number: 5NWSE County: MORGAN

Qtrqtr: NWSE Sec: 5 Twp: 6N Range: 60W Meridian: 6

Latitude: 40.515350 Longitude: -104.115975

FACILITY - API Number: 05-087-00 Facility ID: 227270

Facility Name: ALISSA Number: 1

Qtrqtr: NWSE Sec: 5 Twp: 6N Range: 60W Meridian: 6

Latitude: 40.515350 Longitude: -104.115975

CORRECTIVE ACTIONS:

2 ☒ CA# 124779

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/25/2019

Response: CA COMPLETED

Date of Completion: 05/23/2019

Operator
Comment:

Repair of the erosion control structures was performed on May 23, 2019. See the attached report.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

Any additional disturbance will require reclamation.

OPERATOR COMMENT AND SUBMITTAL

Comment: Additional reclamation activities will be conducted in the next two weeks. These activities will include reseeding of areas disturbed during the repair of the erosion control structures, ripping of the former access road to a depth of 18 inches, reseeding of the access road, reseeding of portions of the former well pad with poor growth, and weed control as necessary.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: David K Nicholson

Signed: _____

Title: Consultant to HRM Resourc

Date: 5/23/2019 3:21:30 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402054232	FIR RESOLUTION SUBMITTED
402054258	BMP Report

Total Attach: 2 Files