

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402058378

Date Received:
05/29/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 17320

Name of Operator: CITY & COUNTY OF DENVER

Address: 8500 PENA BLVD CONCOUR A #4385

City: DENVER State: CO Zip: 80249

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Julie Branting

Phone

303 638 7484

Email

petropro@comcast.net

COGCC INSPECTION SUMMARY:

FIR Document Number: 688401586

Inspection Date: 03/22/2019

FIR Submit Date: 03/22/2019

FIR Status: _____

Inspected Operator Information:

Company Name: CITY & COUNTY OF DENVER

Company Number: 17320

Address: 8500 PENA BLVD CONCOUR A #4385

City: DENVER State: CO Zip: 80249

LOCATION - Location ID: 319712

Location Name: BOX ELDER-62S66W Number: 12NENE County: ADAMS

Qtrqr: NENE Sec: 12 Twp: 2S Range: 66W Meridian: 6

Latitude: 39.897520 Longitude: -104.717040

FACILITY - API Number: 05-001- -00 Facility ID: 208834

Facility Name: BOX ELDER Number: A-1

Qtrqr: NENE Sec: 12 Twp: 2S Range: 66W Meridian: 6

Latitude: 39.897520 Longitude: -104.717040

CORRECTIVE ACTIONS:

1 CA# 123424

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 03/23/2019

Response: CA COMPLETED

Date of Completion: 05/23/2019

Operator Comment: See comments, BP run on 5-23-19. Ticket attached.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Roustabouts at well on 3-22-19, tightened wellhead, no leaks. Started to leak again on 3-26-19, call for water truck. Dumped 80 BBL down well on 3-27-19. Could not loosen cap due to how tubing landed, the master valve was too low. Continued to monitor until rig available. On 5-22-19 Bohler Well Service rigged up on well. Wireline BP run on 5-23-19, set at 8241 ft, 2 sx dump bailed on top. See attached ticket. Form 5 and WBD to follow.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Julie Branting

Signed: _____

Title: Agent

Date: 5/29/2019 3:16:29 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402058387	Wireline field ticket for BP veification
-----------	--

Total Attach: 1 Files