

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2019

Submitted Date:

05/29/2019

Document Number:

695100754**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 307708      Beardslee, Tom      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1801 BROADWAY SUITE 350City: DENVER      State: CO      Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89246	WELL	PR	11/05/1999	GW	071-06826	WORM 33-36	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	PHOTO 2: CURRENT OPERATOR NOT POSTED ON WELL SIGN.		
Corrective Action:	CHANGE OPERATOR NAME TO CURRENT OPERATOR IN ACCORDANCE WITH RULE 210.	Date:	07/29/2019

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	OTHER		
Comment:	PHOTO 1: WELLHEAD/ IMPACTED SOIL AROUND WELLHEAD. PHOTO 3: IMPACTED SOIL AROUND COMPRESSOR SKID. PHOTO 4:: IMPACTED SOIL AROUND ENGINE SKID.		
Corrective Action:	Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907" CA DATE 6/29/19	Date:	06/29/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Compressor	# 1		
Comment:	PHOTO 5: Vacuum pump observed on well without COGCC approval. SOUND STUDY IS NEEDED ON THIS LOCATION.		
Corrective Action:	Provide COGCC with documentation showing approval of use of vacuum pump.	Date:	06/13/2019
Type: Bradenhead	# 1		
Comment:	PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	telemetry equipment		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

<b>Inspected Facilities</b>				
Facility ID: 89246	Type: WELL	API Number: 071-06826	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100755	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4834968">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4834968</a>