

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2019

Submitted Date:

05/30/2019

Document Number:

697300088**FIELD INSPECTION FORM**Loc ID 322868 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Jacob		jacob.evans@nblenergy.com	
Inspections, All		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441780	SPILL OR RELEASE	CL	05/15/2015		-	CHESNUT G 22-3,4 Historical Spill	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Photos attached to document site condition at the time of inspection.

Location**Lease Road:**

Type	Access		
comment:	Recent storms have carried rainwater, mud, and trash onto and over access road.		
Corrective Action	Comply with Rule 603.f .	Date:	06/08/2019

Overall Good: ☐**Emergency Contact Number:**

Comment:	Good.	Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental		
Spill/Remediation:		
Comment:	Multiple monitoring wells damaged.	
Corrective Action:	Perform routine maintenance on monitoring wells.	Date: 06/08/2019
Emission Control Burner (ECB): _____		
Comment:	_____	
Pilot: _____	Wildlife Protection Devices (fired vessels): _____	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Recent storms have caused large amounts of erosion and transported sediment and trash onto and off of location.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 06/11/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697300089	Stormwater Run On	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835466
697300090	Stormwater Run Off	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835467
697300091	Damaged Monitoring Well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4835468