

Fritzler Resources, Inc.

Lease: Jolly

REM: 9401

Date of work Nov 30 thru Dec 4 2018

Date	Ticket No		Gallons	Tons/cu yds	
				Tons	Cu Yds
11/30/2018	4493	NGL	2730		
11/30/2018	3271160	Dads		19.37	18
11/30/2018	3270083	Dads		~18.2	18
11/30/2018	3270072	Dads		~18.2	18
11/30/2018	3269753	Dads		18.14	18
11/30/2018	3270083	Dads		~18.2	18
12/3/2018	3271165	Dads		18.65	18
12/4/2018	3271774	Dads		~18.2	18



NGL Water Solutions DJ, LLC
 8211 W. 20th St.
 Greeley, Co. 80634
 970-373-8503

C6 - SPF

TTS Ticket #: _____

NGL Manifest #: _____

Please fill in each blank and leave top 2 copies at disposal

Date: 11/30/08

NGL Reject Ticket #: _____

Bill to: Operator Transporter

Trucking Co.: D+D Water

Arrival Time: 3:45 AM PM

Truck No.: 22 Trailer No.: _____

Departure Time: 4:45 AM PM

Turnkey Oil Company Hauled For: Fritzler Resources

Lease Name: Jolly Well No: 53124

Company Man: _____ County: Weld

BBL's: 65 Driver's Full Name: Mike Hood

AFE #: _____ (Print)

Fluid Hauled

- Water Based Mud
- Fluid Containing Solids
- Off-Spec Oil
- Oil Based Mud
- Sand
- Displacement Water
- Storage Tank Sludge
- Oil Based Water
- Gel - Frac Tank #: _____
- Tank Bottoms
- Slop
- Other _____

Attempted to unload washout truck, got most of it out. Some solids in bottom not coming out.

Washout

30 Minutes 60 Minutes 90 Minutes

Time in: 3:45 AM PM

Time out: 4:45 AM PM

MAKE A TICKET FOR EACH SEPARATE LOAD HAULED! THANK YOU!

The carrier named hereon certifies that the cargo tank supplied for this shipment is a proper container for the transportation of this commodity and is in accordance with I.C.C specifications and CDOT regulations.

The carrier named hereon acknowledges liability for damages caused by carrier and its agents or representatives to this disposal well for unloading cement or drilling mud at this site or for oil spills, storage tank material, or cellar material in the off loading areas not designated for such off loading.

Driver's Signature

Time in Bay

White: NGLWS Office

Canary: Oil Company

Pink: Transporter

No. DJ 4493

533,50

Mike Hood

M/C

533,50

NON-HAZARDOUS WASTE MANIFEST

19.37 T

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No. <u>11302018A</u>	2. Page 1 of
3. Generator's Name and Mailing Address <u>Friteler Resources P.O. Morgan Co.</u>				
4. Generator's Phone (<u>970</u>) <u>267-9388</u>				
5. Transporter 1 Company Name	6. US EPA ID Number	A. State Transporter's ID		
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter 1 Phone <u>303-622-9499</u>		
9. Designated Facility Name and Site Address <u>D+D Water Service D.A.D.S. Gun Club Rd Aurora Co.</u>	10. US EPA ID Number	C. State Transporter's ID		
		D. Transporter 2 Phone		
		E. State Facility's ID		
		F. Facility's Phone		
11. WASTE DESCRIPTION		12. Containers		13. Total Quantity
		No.	Type	Unit Wt./Vol.
a.				
b. <u>PIP Contaminated Soil</u>				<u>18 yds.</u>
c.				
d.				
G. Additional Descriptions for Materials Listed Above <u>Profile No. # 11494200</u>		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name <u>Gene Friteler</u>		Signature <u>[Signature]</u>	Date Month Day Year <u>11 30 18</u>	
17. Transporter 1 Acknowledgement of Receipt of Materials				
Printed/Typed Name <u>Kyle Roberts</u>		Signature <u>[Signature]</u>	Date Month Day Year <u>11 30 18</u>	
18. Transporter 2 Acknowledgement of Receipt of Materials				
Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space <u>32701160</u>				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name <u>Anthony</u>		Signature <u>[Signature]</u>	Date Month Day Year <u>12 3 19</u>	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

Section 9
NON-HAZARDOUS WASTE MANIFEST

3270083

Print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No. 113020188	2. Page 1 of
3. Generator's Name and Mailing Address <i>Fritzler Resources Ft. Morgan Co.</i>				
4. Generator's Phone (970) 867-9388				
5. Transporter 1 Company Name <i>D+D Water Service</i>	6. US EPA ID Number	A. State Transporter's ID		
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter 1 Phone 303-622-9499		
9. Designated Facility Name and Site Address <i>D.A.D.S. Gen Old Rd. Aspen, Co.</i>	10. US EPA ID Number	C. State Transporter's ID		
		D. Transporter 2 Phone		
		E. State Facility's ID		
		F. Facility's Phone		
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. <i>ETP Contaminated Soil</i>		No.		
		Type		
			18	<i>yds.</i>
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information <i>Profile No. #11494200</i>				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name <i>Gene Fritzler</i>		Signature <i>Gene Fritzler</i>	Date 11/30/18	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name <i>Kyle Bennett</i>		Signature <i>Kyle Bennett</i>	Date 11/30/18	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature	Date	
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name <i>Dustin</i>		Signature <i>Dustin</i>	Date 11/30/18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY



section a
NON-HAZARDOUS WASTE MANIFEST

3270072

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 11302018D	2. Page 1 of	
3. Generator's Name and Mailing Address Fritzel Resources Ft. Morgan, Co.						
4. Generator's Phone (970) 867-9388						
5. Transporter 1 Company Name D+D Water Service	6. US EPA ID Number	A. State Transporter's ID				
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter 1 Phone 303/622/9499				
9. Designated Facility Name and Site Address D.A.D.S. Gen Club Rd. Aurora, Co.		10. US EPA ID Number		C. State Transporter's ID		
				D. Transporter 2 Phone		
				E. State Facility's ID		
				F. Facility's Phone		
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.	
a. E+P Contaminated Soil			No.	Type		
b.					18 yds.	
c.						
d.						
G. Additional Descriptions for Materials Listed Above Profile No. #114942C0			H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information						
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.						
Printed/Typed Name Gene Fritzel				Signature <i>Gene Fritzel</i>	Date Month Day Year 11 30 18	
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name David Fellows				Signature <i>David Fellows</i>	Date Month Day Year 11 30 18	
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name				Signature	Date Month Day Year	
19. Discrepancy Indication Space						
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.						
Printed/Typed Name Dustin				Signature <i>Dustin</i>	Date Month Day Year 11 30 18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY



18-14 T

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No. 11302018C	2. Page 1 of
3. Generator's Name and Mailing Address <i>Fritzel Resources Ft Morgan, Co.</i>				
4. Generator's Phone (<i>970</i>) <i>867-9388</i>				
5. Transporter 1 Company Name <i>D+D Water Service</i>	6. US EPA ID Number	A. State Transporter's ID		
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter 1 Phone <i>303-622-9499</i>		
9. Designated Facility Name and Site Address <i>D.A.D.S. Gon Club Rd. Aurora, Co.</i>		C. State Transporter's ID		
		D. Transporter 2 Phone		
		E. State Facility's ID		
		F. Facility's Phone		
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a.		No.	Type	
<i>E+P Exempt Contaminated Soil</i>				<i>18 yds.</i>
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above <i>Profile No # 114942 CO</i>		H. Handling Codes for Wastes Listed Above <i>Ticket # 3269753</i>		
15. Special Handling Instructions and Additional Information				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name <i>Gene Fritzel</i>			Signature <i>Gene Fritzel</i>	
Date <i>11/30/18</i>				
17. Transporter 1 Acknowledgement of Receipt of Materials				
Printed/Typed Name <i>Darin Kellous</i>			Signature <i>[Signature]</i>	
Date <i>11/30/18</i>				
18. Transporter 2 Acknowledgement of Receipt of Materials				
Printed/Typed Name			Signature	
Date				
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name <i>Chad</i>			Signature <i>CM</i>	
Date <i>11/30/18</i>				

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY



Section 9 NON-HAZARDOUS WASTE MANIFEST

3270083

Print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No. <u>113020188</u>	2. Page 1 of
3. Generator's Name and Mailing Address <i>Fritzler Resources Ft. Morgan Co.</i>				
4. Generator's Phone (<u>970</u>) <u>867-9388</u>				
5. Transporter 1 Company Name <i>D+D Water Service</i>	6. US EPA ID Number	A. State Transporter's ID		
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter 1 Phone <u>303-622-9499</u>		
9. Designated Facility Name and Site Address <i>D.A.D.S. Gen Old Rd. Aurora, Co.</i>	10. US EPA ID Number	C. State Transporter's ID		
		D. Transporter 2 Phone		
		E. State Facility's ID		
		F. Facility's Phone		
11. WASTE DESCRIPTION		12. Containers		13. Total Quantity
		No.	Type	14. Unit Wt./Vol.
a. <i>ETP Contaminated Soil</i>				<u>18</u> yds.
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information <i>Profile No. #11494200</i>				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name <i>Gene Fritzler</i>		Signature <i>[Signature]</i>		Date <u>11</u> <u>30</u> <u>18</u>
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name <i>Kyle Bennett</i>		Signature <i>[Signature]</i>		Date <u>11</u> <u>30</u> <u>18</u>
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature		Month Day Year
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name <i>Dustin</i>		Signature <i>[Signature]</i>		Date <u>11</u> <u>30</u> <u>18</u>

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY



NON-HAZARDOUS WASTE MANIFEST

14651

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No. 12032018A	2. Page 1 of
3. Generator's Name and Mailing Address <i>Pentel Resources P. Morgan, CO</i>				
4. Generator's Phone <i>(970) 867-9388</i>				
5. Transporter 1 Company Name <i>DSD Waste Service</i>	6. US EPA ID Number	A. State Transporter's ID		
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter 1 Phone <i>303-622-9499</i>		
9. Designated Facility Name and Site Address <i>D.A.D.S. Gen Club Rd Morgan, CO</i>		10. US EPA ID Number		
		C. State Transporter's ID		
		D. Transporter 2 Phone		
		E. State Facility's ID		
		F. Facility's Phone		

11. WASTE DESCRIPTION	12. Containers		13. Total Quantity	14. Unit Wt./Vol.
	No.	Type		
a. <i>F.P. Contaminated Soil</i>	<i>22</i>	<i>5.5 Gallon</i>	<i>127.5</i>	<i>127.5 lb</i>
b.				
c. <i>RT</i>	<i>2</i>	<i>470 L</i>	<i>3.70</i>	
d.				<i>116.56</i>

G. Additional Descriptions for Materials Listed Above <i>Profile # 11494200</i>	H. Handling Codes for Wastes Listed Above
--	---

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name <i>Gene Fentler</i>	Signature <i>Gene Fentler</i>	Date Month Day Year
---	----------------------------------	------------------------

17. Transporter 1 Acknowledgement of Receipt of Materials		Date
Printed/Typed Name <i>Paul Hoffman</i>	Signature <i>Paul Hoffman</i>	Month Day Year <i>12 3 18</i>

18. Transporter 2 Acknowledgement of Receipt of Materials		Date
Printed/Typed Name	Signature	Month Day Year

19. Discrepancy Indication Space
(9) *3271165*

20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.		Date
Printed/Typed Name <i>Am Day</i>	Signature <i>Am Day</i>	Month Day Year <i>12 3 18</i>

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

Section 9
NON-HAZARDOUS WASTE MANIFEST

3271744

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>7</i>		Manifest Document No. <i>12042018</i>	2. Page 1 of
3. Generator's Name and Mailing Address <i>Int'l Resources St. Morgan, Co.</i>					
4. Generator's Phone (<i>970</i>) <i>967-9388</i>					
5. Transporter 1 Company Name <i>D+D Water Service</i>		6. US EPA ID Number		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone <i>303-622-9449</i>	
9. Designated Facility Name and Site Address <i>D.A.D.S. Gen Club Rd. Durango CO</i>		10. US EPA ID Number		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone	
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity
			No.	Type	
a. <i>EIP Contaminated Soil</i>					<i>18</i>
b.					<i>yds.</i>
c.					
d.					
G. Additional Descriptions for Materials Listed Above <i>Profile # 11494200</i>			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name <i>Gene Fritcher</i>				Signature <i>Gene Fritcher</i>	
				Date Month <i>12</i> Day <i>4</i> Year <i>18</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name <i>Kyle Hamrick</i>		Signature <i>Kyle Hamrick</i>		Date Month <i>12</i> Day <i>4</i> Year <i>18</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name		Signature		Date Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name <i>Dustin</i>				Signature <i>Dustin</i>	
				Date Month <i>12</i> Day <i>4</i> Year <i>18</i>	

NON-HAZARDOUS WASTE GENERATOR

