

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/05/2019

Submitted Date:

06/05/2019

Document Number:

693500296**FIELD INSPECTION FORM**Loc ID 452914 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458721	WELL	DG	11/27/2018		001-10271	B-Farm LD 18-390HN	DG

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:		
Type	OTHER	
Comment:	Sediment piles from street sweeper dumped along access road with no BMP's in place to control sediment runoff.	
Corrective Action:	Comply with 1002 rules	Date: 06/12/2019

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:		
Type	LOCATION	
Comment:	sound walls	
Corrective Action:		Date:

Venting:		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:		
Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Tracking Pad	Fail			

Comment: [Tracking pad not installed or not adequately maintained to prevent track of material offsite](#)

Corrective Action: [Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.\(2\)F. If material is tracked onto County or public roads, contact the appropriate authority.](#)

Date: 06/06/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday June 5, 2019 at approximately 1154hrs, I Randy Silver conducted an on-site inspection at a Great Western Operating company site B Farm, at Location ID 452914 in Adams County Colorado. While there, I observed a tracking pad issue to a production facility. During this inspection the following possible compliance issues were observed: Tracking pad: Rule 1002 f(2)F Corrective action date of 6-6-19 See photos 1,2,3,4,5,6,7 Storm water: Rule 1002 Corrective action date of 6-12-19 See photo 8 Inspection due to complaint. At time of inspection sediment has been carried onto HWY 7 from BFarm entrance east on HWY 7 to Holly street. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	06/05/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693500297	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4841221