

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402065689

Date Received:

06/05/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10110
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
Address: 1001 17TH STREET #2000
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
PALUCH, KELLY	970-364-2812	cogccinspections@gwogco.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 674902707
Inspection Date: 03/28/2019 FIR Submit Date: 04/08/2019 FIR Status:

Inspected Operator Information:

Company Name: GREAT WESTERN OPERATING COMPANY LLC Company Number: 10110
Address: 1001 17TH STREET #2000
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 424013

Location Name: MARGIL FARMS Number: 25-2D County:
Qtrqr: SWN Sec: 2 Twp: 3N Range: 68W Meridian: 6
W
Latitude: 40.258480 Longitude: -104.977310

FACILITY - API Number: 05-123-00 Facility ID: 424013

Facility Name: MARGIL FARMS Number: 25-2D
Qtrqr: SWN Sec: 2 Twp: 3N Range: 68W Meridian: 6
W
Latitude: 40.258480 Longitude: -104.977310

CORRECTIVE ACTIIONS:

1 CA# 123980

Corrective Action: Perform reclamation in accordance to COGCC 1004 reclamation rules and requirements. Remove the remaining equipment and gravel from the location and access road, perform compaction alleviation, re- contour/re-grade. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards. Operator is directed to perform corrective actions outlined on this inspection report immediately. Doing so may decrease the duration of the alleged violations and the penalties that may be assessed pursuant to Rule 523.

Date: 01/04/2019

Response: CA COMPLETED

Date of Completion: 06/05/2019

Operator Comment: CORRECTIVE ACTION COMPLETED - SEE PHOTOS

COGCC Decision:

COGCC Representative:

2 CA# 123981

Corrective Action: Perform erosion repairs. Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Install or repair required BMPs per Rule 1002.f.

Date: 03/28/2019

Response: CA COMPLETED

Date of Completion: 06/05/2019

Operator Comment: CORRECTIVE ACTION COMPLETED - SEE PHOTOS

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: KELLY PALUCH

Signed:

Title: SR. ADMIN ASST.

Date: 6/5/2019 2:32:17 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402065691	PHOTO #1
402065692	PHOTO #2

Total Attach: 2 Files