

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2019

Submitted Date:

06/06/2019

Document Number:

689802773**FIELD INSPECTION FORM**Loc ID 426365 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

General Comment:**COGCC Inspection Report 689802773 Summary**

On Wednesday 05/29/2019 at approximately 13:00, I, Inspector Emily Waldron, conducted a field inspection at Sandridge Exploration & Production LLC Peterson Ridge 1-20H at 05-057-06515 in Jackson County Colorado.

While there, I performed a follow up inspection to vehicle tracking issues observed in inspection document number 689802622. Vehicle tracking corrective actions have not been resolved.

During this inspection the following possible compliance issues were observed:

Tracking off location occurring onto highway 40 in both directions. No tracking BMPs observed. See photos 1-4. Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F. If material is tracked onto County or public roads, contact the appropriate authority by 5/8/2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection 689802773 report.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Tracking off location occurring onto highway 40 in both directions. No tracking BMPs observed.](#)

Corrective Action: [Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.\(2\)F. If material is tracked onto County or public roads, contact the appropriate authority.](#)

Date: 05/08/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689802774	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4842240