

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/03/2019

Submitted Date:

06/07/2019

Document Number:

688304776

**FIELD INSPECTION FORM**

Loc ID 317130 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 31257  
Name of Operator: FRITZLER RESOURCES INC  
Address: P O BOX 114  
City: FORT MORGAN State: CO Zip: 80701

**Findings:**

- 12 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236633	WELL	PR	06/26/1990	OW	121-09124	WAGERS 11-4	PR

**General Comment:**

[Routine Inspection](#)

[Animal holes on south side of pit berms and badger hole at TB sign, concrete vault need labels and stormwater BMP, partially buried fiberglass tank needs labels \(see attached photos\).](#)

[Wait to spray for weeds when no rain is predicted.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	concrete vault and fiberglass tank need labels maintenance (see attached photos)		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	08/08/2019
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-867-1268	Date:	
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	wire mesh		
Corrective Action:		Date:	

**Equipment:**

Type	#	comment	corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:	shed, bermed		
Corrective Action:			Date:
Type: Prime Mover	# 1		

Comment: <a href="#">electric motor</a>	
Corrective Action:	Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <a href="#">Maintain berms around vault.</a>				
Corrective Action: <a href="#">Install or repair required BMPs per Rule 1002.f.</a>				Date: <a href="#">07/08/2019</a>

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**


Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		39.915300,-103.664920
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type) _____				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				Inadequate
Comment: <span style="color:blue;">badger hole in berm near signs</span>				
Corrective Action: <span style="color:red;">Install or repair required BMPs per Rule 1002.f.</span>				Date: <u>07/08/2019</u>
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:



**Location Construction**

Location ID: 236633 CDP: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** No COAs.

Corrective Action:  Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:**

Corrective Action:  Date: \_\_\_\_\_

**Comment:**

**Corrective Action:**  Date: \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: 236633 Type: WELL API Number: 121-09124 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR. Dec 2018 production last reported to COGCC database.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water                  Lined: NO                  Pit ID:                  Lat:                  Long:

Reference Point: \_\_\_\_\_                  Other: \_\_\_\_\_                  Length: \_\_\_\_\_                  Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type:    Fencing Condition:

Comment: dryland crop field

Corrective Action

Date:

**Netting:**

Netting Type:    Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:                  Oil Accumulation: NO                  2+ feet Freeboard: YES

Comment: animal holes in berms

Corrective Action

Install or repair required BMPs per Rule 1002.f.

Date: 07/08/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688304822	Fritzier Wagers 11-4	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4843213">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4843213</a>
688304823	Fritzier Wagers 11-4 subsidence east of wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4843214">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4843214</a>