

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2019

Submitted Date:

06/10/2019

Document Number:

693500332**FIELD INSPECTION FORM**Loc ID 456747 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Carlisle, J	970-534-6006	COGCCInspections@extracti onog.com	<b>ALL INSPECTIONS</b>
Adamczyk, Megan		megan.adamczyk@state.co.u s	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
463342	WELL	DG	03/27/2019		014-20844	Interchange B N35-20-10N	DG

**General Comment:**

**Inspected Facilities**

Facility ID: 463342 Type: WELL API Number: 014-20844 Status: DG Insp. Status: DG

**Complaint**

Comment: Inspection in response to complaint.  
 Field Inspector Assigned: Randy Silver  
 Complaint Received  
 Date: 06-07-2019  
 Complaint Contacted:  
 Date: 06-07-2019 Time: None  
 Facility ID #: 456747  
 Inspection Document # 693500326  
 Complaint Document #200447415  
 Nature of Complaint: odor  
 Field Inspector Actions:  
 On 06-07-2019, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Odor. The complainant Linda Baird 154882 Quivas st Broomfield CO stated smelling an odor.  
 On 06-07-2019, I attempted to make contact with the complainant who indicated that on 6 -07-19 she stated she had a terrible toxic cleaning solvent smell starting early in the morning which is changed into an overwhelming oil smell .  
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did not smell any unusual odors. I spoke with Broomfield inspectors and they are aware of complaint.  
 At time of inspection, I spoke with Extraction drilling supervisor he stated at time of complaint they were coming out of the hole to change drill bit. Drill cuttings were being loaded and hauled out at time of complaint.  
 Weather conditions: Clear  
 See inspection document #693500326 per my inspection.  
 No violation of COGCC rules were observed at the time of the inspection.  
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
See doc# 693500326 for full inspection.	silverr	06/10/2019