

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402023629

Date Received:

04/26/2019

FIR RESOLUTION FORM

CA Summary:

9 of 9 CAs from the FIR responded to on this Form

9 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10508

Name of Operator: SELECT ENERGY SERVICES LLC

Address: PO BOX 1715

City: GAINESVILLE State: TX Zip: 76241

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Gomez, Jason

jason.gomez@state.co.us

Ries, Barb

970-284-7820

bries@selectenergyservices.com

Koehler, Bob

bob.koehler@state.co.us

R., Harvey

970-324-9342

hgreenwood@selectenergyservices.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688401721

Inspection Date: 03/27/2019

FIR Submit Date: 03/27/2019

FIR Status: _____

Inspected Operator Information:

Company Name: SELECT ENERGY SERVICES LLC

Company Number: 10508

Address: PO BOX 1715

City: GAINESVILLE State: TX Zip: 76241

LOCATION - Location ID: 413438

Location Name: LSWD Number: 1 County: _____

Qtrqtr: NENW Sec: 18 Twp: 3N Range: 64W Meridian: 6

Latitude: 40.231120 Longitude: -104.594900

FACILITY - API Number: 05-123-00 Facility ID: 159372

Facility Name: LSWD #1 Number: _____

Qtrqtr: NENW Sec: 18 Twp: 3N Range: 64W Meridian: 6

Latitude: 40.231120 Longitude: -104.594900

CORRECTIVE ACTIONS:

1 ☒ CA# 123549

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 04/27/2019

Response: CA COMPLETED

Date of Completion: 04/11/2019

Repairs have been completed on acid tank with signage installed, bull plug installed, valve leak repaired. In

Operator Comment: process of removing acid, KCL tanks as we have changed our recycling process for our new contract with customer. Equipment is double walled tank with double walled inlet/outlet PVC lines. Removal is scheduled for May 3rd. photo 6,7,8,9

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 123550

Corrective Action: Comply with rule 603 f

Date: 06/27/2019

Response: CA COMPLETED

Date of Completion: 03/29/2019

Operator Comment: Riser and ECD equipment has been removed photo 16.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

3 ☒ CA# 123551

Corrective Action: Comply with rule 603 f

Date: 06/27/2019

Response: CA COMPLETED

Date of Completion: 05/03/2019

Operator Comment: recycling battery acid / KCL containers are in the process of being removed by May 3. NOT needed in recycling process. At present time, all addressed items for bull plugs, caps, clean up have been addressed photos 6,7,8, 9,10

COGCC Decision: Approved pending re-inspection

COGCC Representative:

4 ☒ CA# 123552

Corrective Action: Install sign to comply with Rule 210.e.

Date: 04/27/2019

Response: CA COMPLETED

Date of Completion: 04/11/2019

Operator Comment: All signage has been reinstalled. photos 5,6,7,10,12,17, 18

COGCC Decision: Approved pending re-inspection

COGCC Representative:

5 ☒ CA# 123553

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e

Date: 04/27/2019

Response: CA COMPLETED

Date of Completion: 03/30/2019

Operator Comment: Completed all oil waste treatment and disposed of in accordance with 907.e. photos 13,14,15

COGCC Decision: Approved pending re-inspection

COGCC Representative:

6 ☒ CA# 123554

Corrective Action: Install sign to comply with Rule 210.e.

Date: 04/27/2019

Response: CA COMPLETED

Date of Completion: 04/11/2019

Operator Comment: tank battery and tank labels/placcards have been replaced , noted in photos, 5,6,7,10,12,17,18

COGCC Decision: Approved pending re-inspection

COGCC Representative:

7 ☒ CA# 123555

Corrective Action: Comply with rule 603 f

Date: 06/27/2019

Response: CA COMPLETED

Date of Completion: 04/02/2019

Operator Comment: removal of unused equipment has been completed. Inspection on recycle tanks (hatch lids off) has been completed all hatch lids have been reinstalled. Connection line to the recycle battery has been reinstalled and completed. Recycle battery was not active at the time of inspection, flow line had been disconnected to ensure no fluids would be charged to the battery unintentional. As we indicated in the inspection, we have a new customer in place for recycling. The recycling battery is in working condition for the recycling project. photos 3,4,5,6,7,9,10,16 have been addressed

COGCC Decision: Approved pending re-inspection

COGCC Representative:

8 ☒ CA# 123556

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 04/27/2019

Response: CA COMPLETED

Date of Completion: 04/03/2019

Operator Comment: acid tank piping repaired, photo 8

COGCC Decision: Approved pending re-inspection

COGCC Representative:

9 ☒ CA# 123557

Corrective Action: Install or repair required BMPs per Rule 1002.f. Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f. (2)F. If material is tracked onto County or public roads, contact the appropriate authority.

Date: 04/27/2019

Response: CA COMPLETED

Date of Completion: 04/10/2019

Operator Comment: Tracking pad has been improved with additional tracking pad rock in entry way forward of cattle guard for displacement of mud and soil from facility. see photo 19, 20 addressed

COGCC Decision: Approved pending re-inspection

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Barbara Ries

Signed: _____

Title: Manager

Date: 4/26/2019 4:15:00 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402023629	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files