

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/12/2019

Submitted Date:

06/12/2019

Document Number:

679704466

**FIELD INSPECTION FORM**

Loc ID 315349 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10539  
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP  
Address: 1125 ESCALANTE DR  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
, Utah Gas Corp	720-425-0303	inspections@utahgascorp.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230676	WELL	SI	05/01/2018	GW	103-08344	FEDERAL D-26-3-101-S	SI

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 6-12-2019 at approximately 14:45, inspector Rick Moran, conducted a routine well inspection at Utah Gas's well Federal D-26-3-101-S in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) MIT
- 2) Seperator / well head sign missing nearest public road. Photo 3. Complete by 8-8-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704466.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Flowline exposed at surface in 2 locations on lease road. Photo 2.		
Corrective ActionL		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery. Missing nearest public road.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/08/2019

<b>Emergency Contact Number:</b>			
Comment:	970-693-6021		
Corrective Action:		Date:	_____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 230676 Type: WELL API Number: 103-08344 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: No current MIT on record or delinquent as required by Rule 326  
Last recorded production September 2016. No record of MIT on file.

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704467	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4848399">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4848399</a>