

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/11/2019

Submitted Date:

06/11/2019

Document Number:

685101092

FIELD INSPECTION FORM

Loc ID 319648 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10548
Name of Operator: HRM RESOURCES II LLC
Address: 410 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Pape, Terry	970-768-5700	tpape@hrmres.com	All inspections
Koehler, Bob		bob.koehler@state.co.us	
Burn, Diana		diana.burn@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
200691	WELL	SI	09/01/1990	ERIW	001-06094	UPRR-SANDEN-EHN 1-17	SI

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume	corrective date
Type: Ancillary equipment	# 1		
Comment:	Electric box		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 200691 Type: WELL API Number: 001-06094 Status: SI Insp. Status: SI

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: <u>DSND</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>06/24/2014</u>
			AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: 5 Year Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: 5 year MIT expired on 6/24/19. No current MIT on record or delinquent as required by Rule 326. 13 days from time of inspection the MIT will be delinquent.

Corrective Action: Contact dnr_cogcengineering@state.co.us with resolution plan. Date: 06/21/2019

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 6/10/19 at approximately 1310 I, Inspector Justin Medina conducted an on-site inspection at HRM Resources II- 001-06094 -UPRR Sanden EHN 1-17 in Adams County Colorado. While there, I observed UIC well During this inspection the following possible compliance issues were observed: 5 year MIT expired on 6/24/19. No current MIT on record or delinquent as required by Rule 326. 13 days from inspection the MIT will be delinquent Contact dnr_cogccengineering@state.co.us with resolution plan. 6/21/19 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Education Inspection</p>	medinaj	06/11/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402070503	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845982
685101093	Pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4845976