

Document Number:
402082152

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10633 Contact Name: Cole Carveth
 Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (303) 774-3979
 Address: 1801 CALIFORNIA STREET #2500 Fax: _____
 City: DENVER State: CO Zip: 80202 Email: cole.carveth@crestonepr.com

For "Intent" 24 hour notice required, Name: Silver, Randy Tel: (720) 827-6688
 COGCC contact: Email: randy.silver@state.co.us

API Number 05-123-20528-00 Well Number: 41-18
 Well Name: KUGEL
 Location: QtrQtr: NENE Section: 18 Township: 2N Range: 67W Meridian: 6
 County: WELD Federal, Indian or State Lease Number: _____
 Field Name: WATTENBERG Field Number: 90750

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.144368 Longitude: -104.925704
 GPS Data:
 Date of Measurement: 06/04/2009 PDOP Reading: 1.5 GPS Instrument Operator's Name: PLinderholm
 Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: 2000
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7446	7460			
J SAND	7868	7920			
NIOBRARA	7232	7248			

Total: 3 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	637	450	637	0	CALC
1ST	7+7/8	4+1/2	11.6	8,017	205	8,017	6,610	CBL
			Stage Tool	5,061	280	5,078	3,750	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7815 with 2 sacks cmt on top. CIPB #2: Depth 7130 with 2 sacks cmt on top.
 CIBP #3: Depth 80 with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 10 sks cmt from 5115 ft. to 5010 ft. Plug Type: CASING Plug Tagged:
 Set 20 sks cmt from 4350 ft. to 4090 ft. Plug Type: CASING Plug Tagged:
 Set 75 sks cmt from 2000 ft. to 1800 ft. Plug Type: STUB PLUG Plug Tagged:
 Set 45 sks cmt from 430 ft. to 290 ft. Plug Type: CASING Plug Tagged:
 Set 25 sks cmt from 80 ft. to 0 ft. Plug Type: CASING Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 (Cast Iron Cement Retainer Depth)

Set 55 sacks half in. half out surface casing from 690 ft. to 585 ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Sandy Ocker

Title: Prod Engineering Tech Date: _____ Email: sandy.ocker@crestonepr.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: _____

COA Type	Description

Attachment Check List

Att Doc Num

Name

402082200

WELLBORE DIAGRAM

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

Stamp Upon
Approval

Total: 0 comment(s)