

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/21/2019

Submitted Date:

06/21/2019

Document Number:

693500486**FIELD INSPECTION FORM**
 Loc ID 456747 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456760	WELL	DG	06/12/2019		014-20780	INTERCHANGE B S22-30-15N	DG

**General Comment:**

**Inspected Facilities**

Facility ID: 456760    Type: WELL    API Number: 014-20780    Status: DG    Insp. Status: DG

**Complaint**

Comment: Inspection in response to complaint.  
 Field Inspector Assigned: Randy Silver  
 Complaint Received  
 Date: 06-19-2019  
 Complaint Contacted:  
 Date: 06-19-2019 Time:  
 Facility ID #: 456747  
 Inspection Document # 693500479  
 Complaint Document #200447448  
 Nature of Complaint: odor  
 Field Inspector Actions:  
 On 06-19-2019, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Odor. The complainant Barb Binder 15583 Quivas Street Broomfield CO stated the issues were occurring outside of her home, from the Interchange A&B pad.  
 On 06-19-2019, I attempted to make contact with the complainant who indicated that on 6-18-19 she experienced an oil odor from the interchange B pad at her house. Odor was strong enough that her throat hurt.  
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did not smell any unusual odors.  
 At time of inspection, I spoke with Extraction drilling supervisor he stated at time of complaint they were drilling and no unusual activity was taking place.  
 Weather conditions: At time of complaint, it was raining off and on. At time of inspection, it was clear and sunny.  
 See inspection document #693500479 per my inspection.  
 No violation of COGCC rules were observed at the time of the inspection.  
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
See Doc#693500479 for full inspection.	silverr	06/21/2019