

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402079977

Date Received:

06/19/2019

FIR RESOLUTION FORM

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

SanJuanCOGCC@bp.com

Beebe, Sabre

970-779-9398

Sabre.Beebe@bpx.com

Labowskie, Steve

steve.labowskie@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 687904826

Inspection Date: 05/28/2019

FIR Submit Date: 05/28/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 326263

Location Name: ANNALA FEDERAL GAS UNIT Number: 15NENW County: LA PLATA
A-M34N8W

Qtrqtr: NENW Sec: 15 Twp: 34N Range: 8W Meridian: N

Latitude: 37.219660 Longitude: -107.733410

FACILITY - API Number: 05-067- -00 Facility ID: 216135

Facility Name: ANNALA FEDERAL A Number: 1

Qtrqtr: NENW Sec: 15 Twp: 34N Range: 8W Meridian: N

Latitude: 37.219660 Longitude: -107.733410

CORRECTIVE ACTIONS:

1 ☒ CA# 125620

Corrective Action: Remove and dispose of contaminated soil/gravel per Rule 1002.f.(2)

Date: 06/28/2019

Response: CA COMPLETED

Date of Completion: 06/17/2019

Operator
Comment:

Stained soils have been removed from location and taken to BPX soil box for remediation at IEI in Farmington NM. All disturbance areas have been back filled with clean soils.

COGCC Decision: Approved

COGCC
Representative:

2 ☒ CA# 125621

Corrective Action: Securely fasten to ensure good mechanical condition per Rule 605.d.

Date: 06/28/2019

Response: CA COMPLETED

Date of Completion: 06/17/2019

Operator
Comment: Operations Technician on location during work to maintain/repair equipment.

COGCC Decision: Approved

COGCC
Representative:

3 ☒ CA# 125622

Corrective Action: Clean up and dispose of affected area per Rule 1002.f.(2).

Date: 06/28/2019

Response: CA COMPLETED

Date of Completion: 06/17/2019

Operator
Comment: Stained soils from exhaust have been removed and taken to BPX soil box for remediation at IEI in Farmington NM. Exhaust hose replaced. See attached

COGCC Decision: Approved

COGCC
Representative:

4 ☒ CA# 125623

Corrective Action: Clean-up and dispose per Rules 907.e. and 1002.f.(2).

Date: 06/28/2019

Response: CA COMPLETED

Date of Completion: 06/17/2019

Operator
Comment: Stained soils around pump jack clean up and taken to BPX soil box for remediation at IEI in Farmington NM. All disturbed areas back filled with clean soils.

COGCC Decision: Approved

COGCC
Representative:

5 ☒ CA# 125624

Corrective Action: Maintain, install or replace all in-place required BMP's per Rule 1002.f.(2)

Date: 06/28/2019

Response: CA COMPLETED

Date of Completion: 06/17/2019

Operator
Comment: Old wattles removed from location and disposed of properly. Berming installed at toe of location to prevent silt migration into vegetation off pad.

COGCC Decision: Approved

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

All corrective actions have been completed document with photos attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 6/19/2019 7:44:04 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402079977	FIR RESOLUTION SUBMITTED
402079984	Completion document

Total Attach: 2 Files