

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402100491

Date Received:

07/09/2019

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 35080

Name of Operator: GRAND MESA OPERATING CO

Address: 1700 N. WATERFRONT PKWY BL 600

City: WICHITA State: KS Zip: 67206

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

MICHAEL REILLY

Phone

316-265-3000

Email

MREILLY@GMOCKS.COM

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200007

Inspection Date: 05/06/2019

FIR Submit Date: 05/08/2019

FIR Status: _____

Inspected Operator Information:

Company Name: GRAND MESA OPERATING CO

Company Number: 35080

Address: 1700 N. WATERFRONT PKWY BL 600

City: WICHITA State: KS Zip: 67206

LOCATION - Location ID: 456610

Location Name: BETTY Number: 1-15 County: _____

Qtrqr: SESW Sec: 15 Twp: 7S Range: 55W Meridian: 6

Latitude: 39.433130 Longitude: -103.540370

FACILITY - API Number: 05-073-00 Facility ID: 456610

Facility Name: BETTY Number: 1-15

Qtrqr: SESW Sec: 15 Twp: 7S Range: 55W Meridian: 6

Latitude: 39.433130 Longitude: -103.540370

CORRECTIVE ACTIONS:

1 ☒ CA# 125000

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 06/08/2019

Response: CA COMPLETED

Date of Completion: 07/06/2019

Operator

Comment:

Halde will be on location today filling drilling pit and leveling location and WW is picking up a pusher shack trailer. BMP's repaired & soil stockpiles put back to normal position. See Pics attached.

COGCC Decision: Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an

COGCC Representative: acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

Interim reclamation appears to have been conducted based on photos provided, however, it is unclear if any stormwater and erosion control BMPs have been implemented to stabilize location until more permanent stabilization controls has been implemented.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: MICHAEL REILLY

Signed: _____

Title: PRESIDENT

Date: 7/9/2019 12:41:23 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402100491	FIR RESOLUTION SUBMITTED
402100496	Reclamation pics
402100497	Reclamation pics
402100499	Reclamation pics
402100500	Reclamation pics
402100502	Reclamation pics
402100507	Reclamation pics

Total Attach: 7 Files