

FORM  
6Rev  
05/18

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



|                                   |    |    |    |
|-----------------------------------|----|----|----|
| DE                                | ET | OE | ES |
| Document Number:<br><br>402054410 |    |    |    |
| Date Received:                    |    |    |    |

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

|   |                                |
|---|--------------------------------|
| OGCC Operator Number: 46290   | Contact Name: Susana Lara-Mesa |
| Name of Operator: KP KAUFFMAN COMPANY INC                                     | Phone: (303) 825-4822          |
| Address: 1675 BROADWAY, STE 2800  | Fax:                           |
| City: DENVER State: CO Zip: 80202   | Email: slaramesa@kpk.com       |
| For "Intent" 24 hour notice required, Name: Silver, Randy Tel: (720) 827-6688 |                                |
| COGCC contact: Email: randy.silver@state.co.us                                |                                |

|   |  |
|---|--|
| API Number: 05-123-10468-00   | Well Number: 2                         |
| Well Name: CHAMPLIN 86 AMOCO F  |  |
| Location: QtrQtr: NESE Section: 4 Township: 1N Range: 68W Meridian: 6 |  |
| County: WELD  | Federal, Indian or State Lease Number: |
| Field Name: SPINDLE   | Field Number: 77900                    |

☒ Notice of Intent to Abandon ☐ Subsequent Report of Abandonment

### Only Complete the Following Background Information for Intent to Abandon

|  |  |
|--|--|
| Latitude: 40.078564  | Longitude: -105.001303   |
| GPS Data:  |  |
| Date of Measurement: 07/25/2007                              | PDOP Reading: 1.8  |
| GPS Instrument Operator's Name: R. Gorka                     |  |
| Reason for Abandonment:                                      | <input type="checkbox"/> Dry <input type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems |
| <input checked="" type="checkbox"/> Other Land use Agreement |  |
| Casing to be pulled:   | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No         Estimated Depth:                               |
| Fish in Hole:  | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No         If yes, explain details below                  |
| Wellbore has Uncemented Casing leaks:                        | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No         If yes, explain details below                  |
| Details:   |  |

### Current and Previously Abandoned Zones

| Formation        | Perf. Top | Perf. Btm | Abandoned Date | Method of Isolation | Plug Depth |
|------------------|-----------|-----------|----------------|---------------------|------------|
| SUSSEX-SHANNON   | 4662      | 4692      |                |                     |            |
| Total: 1 zone(s) |           |           |                |                     |            |

### Casing History

| Casing Type | Size of Hole | Size of Casing | Weight Per Foot | Setting Depth | Sacks Cement | Cement Bot | Cement Top | Status |
|-------------|--------------|----------------|-----------------|---------------|--------------|------------|------------|--------|
| SURF        | 12+1/4       | 8+5/8          | 24              | 618           | 425          | 618        | 0          | VISU   |
| 1ST         | 7+7/8        | 4+1/2          | 10.5            | 5,243         | 530          | 5,243      | 2,603      | CALC   |

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 4640 with 2 sacks cmt on top. CIPB #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at 700 ft. with 30 sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged: ☐

Set 10 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_  
of \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Alan Harrison

Title: VP of Develop. and Prod. Date: \_\_\_\_\_ Email: aharrison@kpk.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_ Date: \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

Expiration Date: \_\_\_\_\_

**COA Type** **Description**

|  |  |
|--|--|
|  |  |
|--|--|

### Attachment Check List

**Att Doc Num** **Name**

|           |                  |
|-----------|------------------|
| 402111312 | WELLBORE DIAGRAM |
| 402111315 | WELLBORE DIAGRAM |

Total Attach: 2 Files

## General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|-------------------|----------------|---------------------|
|                   |                | Stamp Upon Approval |

Total: 0 comment(s)