

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2019

Submitted Date:

07/17/2019

Document Number:

689901011**FIELD INSPECTION FORM**
 Loc ID 308377 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 6295 GREENWOOD PLAZA BLVD #100City: GREENWOOD State: CO Zip: 8111-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ediefitzgerald@tcenergy.us	
Mack, Ronald		ronaldmack@tcenergy.us	
		robfoos@tcenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270570	WELL	PR	08/11/2011	GW	071-07943	APACHE CANYON 1-16	RI

General Comment:

Location inspection.

Location

Lease Road:			
Type	Access		
comment:	There are vehicle ruts along the access road which creates a conveyance for stormwater erosion.		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.	Date:	08/16/2019

Overall Good: ☐

Signs/Marker:			
Type			
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date: _____		

Good Housekeeping:			
Type	OTHER		
Comment:	There is oily waste in the engine skid.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 08/16/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		
Produced Water	WELLHEAD	<= 1 bbl		
Comment:	There is a dripping water leak at the wellhead.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.			Date: 07/19/2019

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689901012	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4881678