

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/18/2019

Submitted Date:

07/18/2019

Document Number:

679704778

FIELD INSPECTION FORM

Loc ID 315122	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 5 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 16700 Name of Operator: CHEVRON USA INC Address: 100 CHEVRON USA INC City: RANGELY State: CO Zip: 81648				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Sanford, Anita		atlx@chevron.com	
Browning, Chuck		chuck.browning@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230289	WELL	IJ	01/01/1999	ERIW	103-07949	HAGOOD L N A-11X	AC

General Comment:

COGCC Inspection Report Summary.

On 7-18-2019 at approximately 11:15, inspector Rick Moran, conducted a follow up inspection at Chevron well L.N. Hagood A 11X in Rio Blanco county of FIR document 693800236.

The following compliance issues were identified as resolved:

- 1) Well head sign.

Additional compliance issues were identified:

- 1) "911" missing on well head sign. Photo 2. Complete by 8-18-2019.
- 2) Deadman marker on ground. Photo 3. Complete by 8-18-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704778.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Missing "911" on sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Install sign to comply with Rule 210.b.	Date: 08/19/2019

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:	One deadman marker lying on ground.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	08/19/2019

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 230289 Type: WELL API Number: 103-07949 Status: IJ Insp. Status: AC**Underground Injection Control**

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: <u>WEBR</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>12/03/2015</u>
			AnnMTReq: _____

Comment: Injection well.

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704779	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4884018