

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/09/2019

Submitted Date:

07/15/2019

Document Number:

688305240

**FIELD INSPECTION FORM**

Loc ID 317121 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 94300  
Name of Operator: WARD & SON\* ALFRED  
Address: P O BOX 737  
City: OGALLALLA State: NE Zip: 69153

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ward, Randy	(308) 280-0100	randy@wardoil.com	
Young, Rob		rob.young@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236505	WELL	SI	01/01/2019	OW	121-08995	BLOMENKAMP 2	SI

**General Comment:**

[Pit Inspection-north toe of NE pit eroding into pasture \(see attached photo\)](#)

**Inspected Facilities**

Facility ID: 236505 Type: WELL API Number: 121-08995 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input style="width:90%;" type="text"/>						Date: _____
Corrective Action: <input style="width:90%;" type="text"/>						
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID: _____	Lat: _____	Long: _____		
Reference Point: _____	Other: _____	Length: _____	Width: _____			
<b>Lining:</b>						
Liner Type: _____		Liner Condition: _____				
Comment: <input style="width:95%;" type="text"/>						Date: _____
Corrective Action <input style="width:95%;" type="text"/>						
<b>Fencing:</b>						
Fencing Type: <u>Livestock</u>		Fencing Condition: <u>Adequate</u>				
Comment: <input style="width:95%;" type="text"/>						Date: _____
Corrective Action <input style="width:95%;" type="text"/>						
<b>Netting:</b>						
Netting Type: _____		Netting Condition: _____				
Comment: <input style="width:95%;" type="text"/>						Date: _____
Corrective Action <input style="width:95%;" type="text"/>						
Anchor Trench Present: _____		Oil Accumulation: <u>NO</u>		2+ feet Freeboard: <u>YES</u>		
Comment: <u>Pit berms on north side of NE pit are eroding into pasture (see attached photo).</u>						Date: <u>08/16/2019</u>
Corrective Action <u>Install stormwater BMPs to prevent offsite sediment transport.</u>						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402109885	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879240">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879240</a>
688305241	Ward & Son* Alfred Blomenkamp 2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879234">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879234</a>
688305242	Ward & Son* Alfred Blomenkamp 2 tank battery sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879235">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879235</a>