

Laramie Energy LLC
API # 05-077-08701
Inspection # 696600408



Sign at Wellhead on location.

Laramie Energy LLC
API # 05-077-08701
Inspection # 696600408



Photo #1 Photo at entrance of location .



Photo #2 Photo at entrance of location

Laramie Energy LLC
API # 05-077-08701
Inspection # 696600408



Photo #3 Photo of tank battery. Weeds in tank berm, Berm is no longer compacted and needs maintenance.



Photo #4 photo at wellheads. Weeds around pump jack

Laramie Energy LLC
API # 05-077-08701
Inspection # 696600408



Photo #5 Photo of erosion channels and sediment moving off on the east side location and down access road



Photo # 6 Photo of erosion channels and sediment moving off on the east side location and down access road

Laramie Energy LLC
API # 05-077-08701
Inspection # 696600408



Photo #7 Photo of erosion sediment moving off on the south side of location



Photo #8 Photo of erosion sediment moving off on the south side of location

Laramie Energy LLC
API # 05-077-08701
Inspection # 696600408



Photo #9 Tank battery berm is in need of maintenance. Also weeds are on location



Photo #10 Tank batter berm is in need of maintenance.

Laramie Energy LLC
API # 05-077-08701
Inspection # 696600408



Photo #11 Photo of erosions sediment moving off on the west side of location, causing a channel



Photo #12 Photo of erosions sediment moving off on the west side of location, causing a deep channel

Laramie Energy LLC
API # 05-077-08701
Inspection # 696600408



Photo #13 Photo of the north side of location. Erosions and sediment have run off location and choked out all vegetation. Weeds on location around gas meter run.



Photo #14 Erosion channel and sediment moving off on the NW side of location. All vegetation has been choked out of the area.

Laramie Energy LLC
API # 05-077-08701
Inspection # 696600408



Photo #15 Photo of the north side of location. Erosions and sediment have run off location and choked out all vegetation



Photo #16 Photo of north side of location. Erosions and sediment have run off location and choked out all vegetation