

T1N, R65W

NW. COR.
SEC. 30, T1N, R65W
FOUND 2 1/2" ALUM. CAP
P.L.S. NO. 28656

BOTTOM
OF HOLE

NE. COR.
SEC. 30, T1N, R65W
FOUND 2" ALUM. CAP
ILLEGIBLE

N 89°02'54" E 2643.34' (M)

N 89°01'41" E 2633.27' (M)

N. 1/4 COR.
SEC. 30, T1N, R65W
FOUND 3 1/4" ALUM. CAP
L.S. NO. 27269

2468'

SURFACE LOCATION
GROUND ELEVATION= 4999.1'
LATITUDE= 40.015686°
LONGITUDE= -104.709598°
1/4 1/4: SE1/4 SW1/4

LANDING POINT
LATITUDE= 40.016325°
LONGITUDE= -104.706269°
1/4 1/4: SW1/4 SE1/4

BOTTOM HOLE LOCATION
LATITUDE= 40.029596°
LONGITUDE= -104.706046°
1/4 1/4: NW1/4 NE1/4

N 00°16'28" W
1313.05' (M)

N. 1/16 COR.
SEC. 25, T1N, R66W &
SEC. 30, T1N, R65W
FOUND 2 1/2" ALUM. CAP
P.L.S. NO. 38304

NO. 1

N 00°16'18" W
1328.61' (M)

N 00°08'23" W
2646.86' (M)

N 00°13'42" E 4835'

N 00°13'34" E 2653.16' (M)

W. 1/4 COR.
SEC. 30, T1N, R65W
FOUND 3 1/4" ALUM. CAP
ILLEGIBLE

N 89°09'34" E
2637.12' (M)

30

N 89°09'34" E
2616.25' (M)

CENTER 1/4 COR.
SEC. 30, T1N, R65W
SET 2 1/2" ALUM. CAP
P.L.S. NO. 38512

E. 1/4 COR.
SEC. 30, T1N, R65W
FOUND 2 1/2" ALUM. CAP
P.L.S. NO. 36060

N 00°15'58" W
1320.87' (M)

JOHNSON
01N-65W-30-10H

SURFACE LOCATION

NO. 2

N 00°08'23" W
1323.98' (M)

N 00°08'14" W
1323.81' (M)

LANDING POINT

N 00°13'52" E 2653.27' (M)

S. 1/16 COR.
SEC. 25, T1N, R66W &
SEC. 30, T1N, R65W
FOUND 2" ALUM. CAP
L.S. NO. 25937

N 00°14'58" W
1321.00' (M)


N 89°17'13" E 2631.55' (M)

230'

S. 1/4 COR.
SEC. 30, T1N, R65W
FOUND 2 1/2" ALUM. CAP
L.S. NO. 26952

N 89°16'28" E 2599.08' (M)

SE. COR.
SEC. 30, T1N, R65W
FOUND 2 1/2" ALUM. CAP
L.S. NO. 23027



CERTIFICATE OF SURVEYOR:


THIS IS TO CERTIFY THAT THE ABOVE PLAN WAS PREPARED FROM FIELD NOTES OF ACTUAL SURVEY MADE BY ME OR UNDER MY SUPERVISION AND TO THE BEST OF MY KNOWLEDGE AND BELIEF THIS CERTIFICATE DOES NOT REPRESENT A LAND SURVEY OR IMPROVEMENT SURVEY AS DEFINED BY C.R.S. 19-51-302 AND CANNOT BE RELIED UPON TO DETERMINE OWNERSHIP.

Randall K. French
38512
PROFESSIONAL LAND SURVEYOR
9/18/18
RANDALL K. FRENCH
PROFESSIONAL LAND SURVEYOR
COLORADO REGISTRATION NUMBER: 38512

NOTICE:
ACCORDING TO COLORADO STATE LAW YOU MUST COMPLY WITH ALL APPLICABLE LEGAL ACTION BASED UPON ANY DEFECT IN THIS SURVEY WITHIN THREE YEARS AFTER YOU FIRST DISCOVER SUCH DEFECT. IN NO EVENT MAY ANY ACTION BASED UPON ANY DEFECT IN THIS SURVEY BE COMMENCED MORE THAN TEN YEARS FROM THE DATE ON THE CERTIFICATION SHOWN HEREON.

WELL DISTANCES:

BUILDING: ±854' E
BUILDING UNIT: ±1697' W
PUBLIC ROAD: ±232' S
ABOVE GROUND UTILITY: ±272' S
RAILROAD: ±2746' SE
PROPERTY LINE: ±230' S
HIGH OCCUPANCY BUILDING UNIT: ±4258' S
DESIGNATED OUTSIDE ACTIVITY AREA: 5280'+



SCALE: 1" = 1000'

NOTES:

- ▲ INDICATES SECTION CORNER.
- INDICATES CALCULATED CORNER.
- ELEVATION BASED ON NAVD88 (GEOID12B).
- BASIS OF BEARING DERIVED FROM COLORADO COORDINATE SYSTEM OF 1983 NORTH ZONE.
- ALL MEASURED DISTANCES ARE GRID.
COMBINED SCALE FACTOR: .99972845 CALCULATED FROM THE W. 1/4 CORNER OF SECTION 30, T1N, R65W.
- OPERATOR: PRESTON KNUITSEN / PDOP = 1.5.
- SEE ADDENDUM TO WELL LOCATION CERTIFICATE FOR EXISTING IMPROVEMENTS WITHIN 500' OF THE WELL PAD. WELL FOOTAGES ARE MEASURED AT RIGHT ANGLES TO THE SECTION LINES.
- THE BOTTOM OF HOLE BEARS N00°13'42"E, 4835' FROM THE LANDING POINT.
- NO. 1 & NO. 2 AS SHOWN HEREON ARE GOVERNMENT LOTS 1 & 2 PER THE ORIGINAL GLO SURVEY.

WELL PAD - JOHNSON 01N-65W-30

JOHNSON 01N-65W-30-10H
WELL LOCATION CERTIFICATE
230' FSL & 1835' FWL (SESW) (SURFACE)
460' FSL & 2468' FEL (SWSE) (LANDING POINT)
1' FNL & 2468' FEL (NWNE) (BOTTOM)
LOCATED IN SECTION 30
T1N, R65W, 6TH P.M.
WELD COUNTY, COLORADO



5950 Cedar Springs Road, Suite 200
Dallas, Texas 75235



SHERIDAN OFFICE
1095 Saberton Avenue
Sheridan, Wyoming 82801
Phone 307-674-0609

LOVELAND OFFICE
6706 North Franklin Avenue
Loveland, Colorado 80538
Phone 970-776-4331

DRAFTED BY:	LMO	CHECKED BY:	RKF
DATE DRAFTED:	1/30/18	DATE SURVEYED:	7/6/18
REVISED:	9/18/18	FILE NAME:	17-171