

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/08/2019

Submitted Date:

08/09/2019

Document Number:

696200550

**FIELD INSPECTION FORM**Loc ID 330359 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Evins, Bret		bret.evins@state.co.us	
,		dnr_cogccenforcement@state.co.us	
,		regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251165	WELL	SI	06/01/2016	WA	123-18968	SOONER 21-16-9	RI
330359	LOCATION	AC			-	SOONER-68N58W 21SESE	RI

**General Comment:**

This is a follow-up good housekeeping inspection.

This inspection is to document compliance for the following corrective actions:

603.f: Ongoing weed management and monitoring.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	1002.e requires that access roads to be located, adequately sized, constructed, and maintained so as to reasonably control dust and minimize erosion, alteration of natural features, removal of surface materials, and degradation due to contamination. 1002.e(4) requires that vehicles not travel outside of the original access road boundary.  Access road has not been adequately constructed, or with sufficient BMPs, to allow for proper stormwater discharge per 1002.f, and to allow for vehicle travel on access road; Operator has travelled beyond the designated access road onto adjacent lands creating additional disturbance.		
Corrective Action:	Comply with 1002.e and restrict vehicle use to the access road in order to mitigate additional unnecessary disturbances and alteration of natural features. Construct access road, install or repair required BMPs to stop further disturbance and to ensure existing access road remains in proper functioning condition.	Date:	08/16/2019

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Previous inspections documented noxious weeds ((Diffuse Knapweed, Centaurea diffusa) on location and required operator to conduct weed management and remove.  Diffuse Knapweed has been allowed to re-establish on location and access road. Original corrective action and date is being provided as Operator has failed to conduct sufficient ongoing noxious weed monitoring and management required by previous inspections.		
Corrective Action:	Properly remove and control noxious weeds. Ongoing weed management and monitoring is required, and needs to occur in accordance to COGCC rules and regulations	Date:	06/22/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 251165 Type: WELL API Number: 123-18968 Status: SI Insp. Status: RIFacility ID: 330359 Type: LOCATION API Number: - Status: AC Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696200551	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904903">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904903</a>