

RECEIVED

MAY 9 1974

STATE OF COLORADO
DEPARTMENT OF NATURAL RESOURCES
OIL AND GAS CONSERVATION COMMISSION

COLO. OIL & GAS CONS. COMM.

Room 237, Columbine Building
1845 Sherman Street
Denver, Colorado 80203

April 30, 1974

Last report came in Nov. 17, 1972

Delaney Petroleum Company
695 East 27th St.
Long Beach, California

To complete at a later date- Spring of 1973 on
report.....

Present status of this well Please

Gentlemen:

We have not received reports, as checked below, for the following well.

COMMENTS:

23 A GettyO Amoco..... 3-1NG 102 W- Rangely, Rio Bl.

- | | | |
|--------------------------|---------|---|
| <input type="checkbox"/> | Form 1 | Designation of Agent |
| <input type="checkbox"/> | Form 2 | Application for Permit to Drill, Deepen, or
Re-Enter and Operate |
| <input type="checkbox"/> | Form 3 | Bonding Requirements |
| <input type="checkbox"/> | Form 4 | Sundry Notices and Reports on Wells |
| <input type="checkbox"/> | Form 5 | Well Completion or Recompletion Report and Log |
| <input type="checkbox"/> | Form 10 | Certificate of Clearance |
| <input type="checkbox"/> | Form 15 | Application for Permit to use Earthen Pit |
| <input type="checkbox"/> | OTHERS: | |

Please submit the above requested reports to this office as soon as possible.

MAY 6 1974

OIL AND GAS CONSERVATION COMMISSION

D.V. Rogers
D.V. Rogers, Director

We have been drilling off and on on this well since last fall. The hole is now 2015 feet deep and the formation looks as though we are near a producing zone. However, the cable rig we were using is too small to go any deeper. We will proceed with the drilling if and when we can get a larger rig. Since we are no longer permitted to use rotary rigs in the Rangely area large cable rigs are very difficult to obtain. Will advise when we complete the well.



00039168

Geo. B. McAllister, Agent