

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/02/2019

Submitted Date:

08/09/2019

Document Number:

692401237

FIELD INSPECTION FORM

Loc ID 314231 Inspector Name: Colby, Lou On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Patterson, Chris	970 675 3814	SPWU@chevron.com	Reclamation Insp
Vaughn, Danny		dannyvaughn@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228093	WELL	TA	10/01/2018	ERIW	103-01008	FEE 50	RI

General Comment:

This is an Interim Reclamation focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed are still applicable. This Inspection is conducted solely to link an uncovered/open Lateral Shut Off valve can to an API# in order to give a Corrective Action to Cover/Close Cellar. Valve Can was located at road T to Northeast of Chevron office building.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Other

#

corrective date

Comment: Cover was off Lateral Shut off Valve Can; with no egress for wildlife. Several desiccated rabbit carcasses were seen at bottom of cellar. Operator was contacted, came out immediately, was shown open Valve Can and indicated Cover would be installed as soon as work crew could be contacted, before day end.

Corrective Action: Install Cellar/Valve Can cover to maximize safety and wildlife welfare. If holes remain that would allow wildlife ingress install means of wildlife egress.

Date: 08/02/2019

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 228093 Type: WELL API Number: 103-01008 Status: TA Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402139260	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904287
692401246	Inspection Photos RI	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904280