

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402146766

Date Received:

08/16/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10559  
Name of Operator: SOUTHLAND ROYALTY COMPANY LLC  
Address: 400 WEST 7TH STREET  
City: FORT WORTH State: TX Zip: 76102

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Gallenbeck, Danny		dgallenbeck@ctfieldsvcs.com
Blaylock, Connie		cblaylock@mspartners.com
Allman, Stephanie	307-382-4005	stephanie_allman@eogresources.com
Elgin, Jerry		jelgin@mspartners.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689802617  
Inspection Date: 05/02/2019 FIR Submit Date: 05/08/2019 FIR Status:

Inspected Operator Information:

Company Name: EOG Y RESOURCES INC Company Number: 97810  
Address: 105 SOUTH 4TH ST  
City: ARTESIA State: NM Zip: 88210

LOCATION - Location ID: 313308

Location Name: Landing Strip Unit-69N90W Number: 6NWSW County: MOFFAT  
Qtrqr: NWS Sec: 6 Twp: 9N Range: 90W Meridian: 6  
W  
Latitude: 40.764000 Longitude: -107.539310

FACILITY - API Number: 05-081-00 Facility ID: 285957

Facility Name: LANDING STRIP FEDERAL Number: 1  
Qtrqr: NWS Sec: 6 Twp: 9N Range: 90W Meridian: 6  
W  
Latitude: 40.764000 Longitude: -107.539310

CORRECTIVE ACTIIONS:

1 CA# 125014

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/17/2019

Response: CA COMPLETED

Date of Completion: 08/15/2019

Operator Comment: This is the second corrective action response (ref CA #125014 "Not Approved" on 8/1/19).  
The Corrective Action has been completed as of 8/15/19.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: As of 8/15/19, netting has been cut and the wattles keyed-in over the slope, below the slope, and on the northwest corner of the location. New growth is evident over the area that was repaired and reseeded by SRC in May 2019. Photos attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Connie Blaylock

Signed: \_\_\_\_\_

Title: Regulatory Analyst

Date: 8/16/2019 9:01:52 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402146808	PHOTO 1
402146809	PHOTO 2
402146810	PHOTO 3
402146811	PHOTO 4
402146817	PHOTO 5
402146825	PHOTO 6
402146829	PHOTO 7
402146834	PHOTO 8
402146838	PHOTO 9
402146840	PHOTO 10
402146842	PHOTO 11

Total Attach: 11 Files