

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402147617  
Date Received:  
08/16/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
.		robfoos@tcenergyllc.com ediefitzgerald@tcenergyllc.com ronaldmack@tcenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901009  
Inspection Date: 07/15/2019 FIR Submit Date: 07/17/2019 FIR Status:

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 312069

Location Name: APACHE CANYON-634S67W Number: 8NWNE County: LAS ANIMAS  
Qtrqtr: NWNE Sec: 8 Twp: 34S Range: 67W Meridian: 6  
Latitude: 37.104180 Longitude: -104.908300

FACILITY - API Number: 05-071-00 Facility ID: 217393

Facility Name: APACHE CANYON Number: 8-2  
Qtrqtr: NWNE Sec: 8 Twp: 34S Range: 67W Meridian: 6  
Latitude: 37.104180 Longitude: -104.908300

CORRECTIVE ACTIONS:

1 CA# 128211

Corrective Action: Install or repair required BMPs per Rule 1002.f. Date: 08/16/2019

Response: CA COMPLETED Date of Completion: 08/02/2019

The access road was regraded to eliminate the potholes. The bar ditch was dominated to direct run off to the

Operator Comment: culvert inlet.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 128212

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.  
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition,  
inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 08/16/2019

Response: CA COMPLETED \_\_\_\_\_

Date of Completion: 08/15/2019

Operator Comment: The fluid accumulation was removed from the skid. All fittings were securely fastened, all repairs are complete.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**3** CA# 128244

Corrective Action: Remove supplies and trash.  
Comply with Rule 603.f .

Date: 08/16/2019

Response: CA COMPLETED \_\_\_\_\_

Date of Completion: 08/12/2019

Operator Comment: All unused parts were removed from the location.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**4** CA# 128448

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 07/19/2019

Response: CA COMPLETED \_\_\_\_\_

Date of Completion: 08/15/2019

Operator Comment: The impacted soil was removed from location.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: \_\_\_\_\_

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files