

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402150254

Date Received:

08/20/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Bill Scofield		regulatory@foundationenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696101172
Inspection Date: 07/22/2019 FIR Submit Date: 07/23/2019 FIR Status:

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC Company Number: 10112
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 327361

Location Name: SOONER UNIT-68N58W Number: 21SEnw County:
Qtrqtr: SENW Sec: 21 Twp: 8N Range: 58W Meridian: 6
Latitude: 40.649590 Longitude: -103.870110

FACILITY - API Number: 05-123-00 Facility ID: 327361

Facility Name: SOONER UNIT-68N58W Number: 21SEnw
Qtrqtr: SENW Sec: 21 Twp: 8N Range: 58W Meridian: 6
Latitude: 40.649590 Longitude: -103.870110

CORRECTIVE ACTIONS:

1 CA# 128429

Corrective Action: Post capacity on or near partially buried steel tank in pit area.
Comply w/ Rule 210.d.
See photo #37.

Date: 09/23/2019

Response: CA COMPLETED Date of Completion: 08/15/2019

Operator Comment: Corrected

COGCC Decision: _____

COGCC
Representative:

2 CA# 128430

Corrective Action: Remove and/or remediate stained soil around wellsite.
Comply w/ Rule 907.e.
See photos #1-4.

Date: 08/22/2019

Response: CA COMPLETED

Date of Completion: 08/15/2019

Operator
Comment: Removed stained soil around wellsite

Removed stained soil around wellsite

COGCC Decision: _____

COGCC
Representative:

3 CA# 128431

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.
Corrective Action date: 08/15/2016.
Original Corrective Action date remains applicable.
See photos #31-34.

Date: 08/15/2016

Response: CA COMPLETED

Date of Completion: 08/15/2019

Operator
Comment: Fastened all valves, removed stained equipment/ floor in injection pump house.

Fastened all valves, removed stained equipment/ floor in injection pump house.

COGCC Decision: _____

COGCC
Representative:

4 CA# 128432

Corrective Action: Remove, manage, & control weeds on floor of produced H2O pit. Comply with Rule 603.f.
See photo #38.

Date: 08/02/2019

Response: CA COMPLETED

Date of Completion: 08/15/2019

Operator
Comment: Removed weeds on floor of produced water pit

Removed weeds on floor of produced water pit

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions resolved

Corrective actions resolved

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Alyssa Beard

Signed: _____

Title: HSE Manager

Date: 8/20/2019 10:12:20 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402150265	Sooner 6-21
402150266	Sooner 6-21 2

Total Attach: 2 Files