

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/03/2019

Submitted Date:

09/03/2019

Document Number:

699300078

**FIELD INSPECTION FORM**

Loc ID 317994 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 79905  
Name of Operator: SMITH OIL PROPERTIES INC  
Address: PO BOX 219  
City: BYERS State: CO Zip: 80103

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Shelley, Vicki	303-825-7405	smithoilprop@aol.com	
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240341	WELL	SI	01/01/2019	ERIW	123-08129	ANDREWS(LANYARD WATERFLOOD) 23-18	SI

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Other		
comment:	No road in the middle of grass field at a Sod farm		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		Date: _____
Corrective Action:	<input type="text"/>		
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil/possible leak by wellhead.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Properly treat or dispose of oily waste in accordance with 907.e.		Date: <u>07/06/2019</u>
Type	WEEDS		
Comment:	Weeds overgrown around WH		
Corrective Action:	Comply with Rule 603.f		Date: <u>09/13/2019</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Fabricated fencing		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:	appears to be plumbed to surface		
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 240341 Type: WELL API Number: 123-08129 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Tuesday 9/3/2019 at approximately 1400 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Andrews Lanyard Waterflood #23-18 Smith Oil Properties, at API # 05-123-08129 in Weld County Colorado.                      While there, I observed a UIC well. Scout card show it to be SI and at the time of this inspection valves appear to be open.                      During this inspection the following possible compliance issues were observed:                      Follow up inspection to Doc. # 685101073 Stained soil/possible leak by wellhead have not been addressed. Securely fasten all valves, pipes and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d                      For localized spotting of oily waste – “ Properly treat or dispose of oily waste in accordance with 907.e CA date 7/6/2019. See attached photo #3                      Housekeeping: Weeds overgrown throughout well site.                      Rule 603.f CA date 9/13/2019 see attaches photos #1, 2 and 3.                      Location is dry, weather is cloudy.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      Continuing education COGCC Inspection Report Summary Inspection.                      This is a summary of inspection report.</p>	revasr	09/03/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300079	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927619">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4927619</a>