


# T6N, R66W



**SURFACE HOLE LOCATION**  
 GROUND ELEVATION= 4696.9'  
 LATITUDE= 40.461170°  
 LONGITUDE= -104.740596°  
 1/4 1/4: SW1/4 NE1/4  
**TOP OF PRODUCTIVE ZONE**  
 LATITUDE= 40.459640°  
 LONGITUDE= -104.734294°  
 1/4 1/4: SW1/4 NW1/4  
**BOTTOM OF PRODUCTIVE ZONE**  
 LATITUDE= 40.459552°  
 LONGITUDE= -104.698408°  
 1/4 1/4: SE1/4 NE1/4  
**BOTTOM HOLE LOCATION**  
 LATITUDE= 40.459551°  
 LONGITUDE= -104.698048°  
 1/4 1/4: SE1/4 NE1/4

### CERTIFICATE OF SURVEYOR:

THIS IS TO CERTIFY THAT THE ABOVE PLAT WAS PREPARED FROM FIELD NOTES OF ACTUAL SURVEY MADE BY ME OR UNDER MY SUPERVISION AND THAT THE SAME IS TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF. THIS CERTIFICATE DOES NOT REPRESENT A LAND SURVEY PLAT OR IMPROVEMENT SURVEY PLAT AS DEFINED BY C.S. 2011-302 AND CANNOT BE RELIED UPON TO DETERMINE OWNERSHIP.

*Randall K. French*  
 RANDALL K. FRENCH  
 PROFESSIONAL LAND SURVEYOR  
 COLORADO REGISTRATION NUMBER: 38512  
 8/9/19

**NOTICE:**  
 ACCORDING TO COLORADO STATE LAW YOU MUST COMMENCE LEGAL ACTION BASED UPON ANY DEFECT IN THIS SURVEY WITHIN THREE YEARS AFTER YOU FIRST DISCOVER SUCH DEFECT. IN NO EVENT MAY ANY ACTION BASED UPON ANY DEFECT IN THIS SURVEY BE COMMENCED MORE THAN TEN YEARS FROM THE DATE ON THE CERTIFICATION SHOWN HEREON.

### WELL DISTANCES:

**BUILDING:** ±1070' S  
**BUILDING UNIT:** ±1182' S  
**HIGH OCCUPANCY BUILDING UNIT:** 5280'+  
**DESIGNATED OUTSIDE ACTIVITY AREA:** 5280'+  
**PUBLIC ROAD:** ±1062' NE  
**ABOVE GROUND UTILITY:** ±1055' NE  
**RAILROAD:** 5280'+  
**PROPERTY LINE:** ±254' E  
**SCHOOL FACILITY:** 5280'+  
**SCHOOL PROPERTY LINE:** 5280'+  
**CHILD CARE CENTER:** 5280'+

### NOTES:

- ▲ INDICATES SECTION CORNER.
- INDICATES CALCULATED CORNER.
- DRAWING LATITUDE AND LONGITUDE COORDINATES ARE NAD 83 (2011)(EPOCH:2010). ELEVATION BASED ON NAVD88 (GEOID12B).
- BASIS OF BEARING DERIVED FROM COLORADO COORDINATE SYSTEM OF 1983 NORTH ZONE.
- ALL MEASURED DISTANCES ARE GRID. COMBINED SCALE FACTOR: .99974177 CALCULATED FROM THE E. 1/4 CORNER OF SECTION 26, T6N, R66W.
- OPERATOR: PRESTON KNUTSEN / PDOP = 1.2.
- SEE ADDENDUM TO WELL LOCATION CERTIFICATE FOR EXISTING IMPROVEMENTS WITHIN 500' OF THE WELL PAD.
- WELL FOOTAGES ARE MEASURED AT RIGHT ANGLES TO THE SECTION LINES.
- THE BOTTOM HOLE LOCATION BEARS N89°40'37"E, 10086' FROM THE TOP OF PRODUCTIVE ZONE.

### WELL PAD - CHALK-SEELEY FEDERAL 7-26 PAD

SEELEY 108-14N-30B-L  
 WELL LOCATION CERTIFICATE  
 1973' FNL & 1595' FEL SWNE (SURFACE HOLE LOCATION)  
 LOCATED IN SECTION 26  
 2528' FNL & 150' FWL SWNW (TOP OF PRODUCTIVE ZONE)  
 LOCATED IN SECTION 25  
 T6N, R66W, 6TH P.M.  
 2525' FNL & 460' FEL SENE (BOTTOM OF PRODUCTIVE ZONE)  
 2525' FNL & 360' FEL SENE (BOTTOM HOLE LOCATION)  
 LOCATED IN SECTION 30, T6N, R65W, 6TH P.M.  
 WELD COUNTY, COLORADO




**CONSULTING, LLC**  

**SHERIDAN OFFICE**  
 1095 Saberton Avenue  
 Sheridan, Wyoming 82801  
 Phone 307-674-0609  
**LOVELAND OFFICE**  
 6706 North Franklin Avenue  
 Loveland, Colorado 80538  
 Phone 970-776-4331

DRAFTED BY: LMO	CHECKED BY: RKF	SHEET NO: <b>1</b> 1 OF 3
DATE DRAFTED: 9/26/17	DATE SURVEYED: 7/7/17	
REVISED: 8/9/19	FILE NAME: 17-41	

K:\SYNERGY RESOURCES\2017\7-26 CHALK-SEELEY 7-26 PLATS\dwg\8/9/2019 9:46:03 AM.lbr





**SURFACE HOLE LOCATION**  
 GROUND ELEVATION= 4696.9'  
 LATITUDE= 40.461170°  
 LONGITUDE= -104.740596°  
 1/4 1/4: SW1/4 NE1/4  
**TOP OF PRODUCTIVE ZONE**  
 LATITUDE= 40.459640°  
 LONGITUDE= -104.734294°  
 1/4 1/4: SW1/4 NW1/4  
**BOTTOM OF PRODUCTIVE ZONE**  
 LATITUDE= 40.459552°  
 LONGITUDE= -104.698408°  
 1/4 1/4: SE1/4 NE1/4  
**BOTTOM HOLE LOCATION**  
 LATITUDE= 40.459551°  
 LONGITUDE= -104.698048°  
 1/4 1/4: SE1/4 NE1/4

**CERTIFICATE OF SURVEYOR:**

THIS IS TO CERTIFY THAT THE ABOVE PLAT WAS PREPARED FROM FIELD NOTES OF ACTUAL SURVEY MADE BY ME OR UNDER MY SUPERVISION AND THAT THE SAME ARE TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF. THIS CERTIFICATE DOES NOT REPRESENT A LAND SURVEY PLAT OR IMPROVEMENT SURVEY PLAT AS DEFINED BY C.S. 2011-302 AND CANNOT BE RELIED UPON TO DETERMINE OWNERSHIP.

*Randall K. French*  
 RANDALL K. FRENCH  
 PROFESSIONAL LAND SURVEYOR  
 COLORADO REGISTRATION NUMBER: 38512  
 8/9/19

**NOTICE:**  
 ACCORDING TO COLORADO STATE LAW YOU MUST COMMENCE LEGAL ACTION BASED UPON ANY DEFECT IN THIS SURVEY WITHIN THREE YEARS AFTER YOU FIRST DISCOVER SUCH DEFECT. IN NO EVENT MAY ANY ACTION BASED UPON ANY DEFECT IN THIS SURVEY BE COMMENCED MORE THAN TEN YEARS FROM THE DATE ON THE CERTIFICATION SHOWN HEREON.

**WELL DISTANCES:**

- BUILDING: ±1070' S
- BUILDING UNIT: ±1182' S
- HIGH OCCUPANCY BUILDING UNIT: 5280'+
- DESIGNATED OUTSIDE ACTIVITY AREA: 5280'+
- PUBLIC ROAD: ±1062' NE
- ABOVE GROUND UTILITY: ±1055' NE
- RAILROAD: 5280'+
- PROPERTY LINE: ±254' E
- SCHOOL FACILITY: 5280'+
- SCHOOL PROPERTY LINE: 5280'+
- CHILD CARE CENTER: 5280'+

**NOTES:**

1. ▲ INDICATES SECTION CORNER.
2. ● INDICATES CALCULATED CORNER.
3. DRAWING LATITUDE AND LONGITUDE COORDINATES ARE NAD 83 (2011)(EPOCH:2010).
4. ELEVATION BASED ON NAVD88 (GEOID12B).
5. BASIS OF BEARING DERIVED FROM COLORADO COORDINATE SYSTEM OF 1983 NORTH ZONE.
6. ALL MEASURED DISTANCES ARE GRID. COMBINED SCALE FACTOR: .99974177 CALCULATED FROM THE E. 1/4 CORNER OF SECTION 26, T6N, R66W.
7. OPERATOR: PRESTON KNUTSEN / PDOP = 1.2.
8. SEE ADDENDUM TO WELL LOCATION CERTIFICATE FOR EXISTING IMPROVEMENTS WITHIN 500' OF THE WELL PAD.
9. WELL FOOTAGES ARE MEASURED AT RIGHT ANGLES TO THE SECTION LINES.
10. THE BOTTOM HOLE LOCATION BEARS N89°40'37"E, 10086' FROM THE TOP OF PRODUCTIVE ZONE.
11. NO. 1 & NO. 2 AS SHOWN HEREON ARE GOVERNMENT LOTS 1 & 2 PER THE ORIGINAL GLO SURVEY

**WELL PAD - CHALK-SEELEY FEDERAL 7-26 PAD**

SEELEY 108-14N-30B-L  
 WELL LOCATION CERTIFICATE  
 1973' FNL & 1595' FEL SWNE (SURFACE HOLE LOCATION)  
 LOCATED IN SECTION 26  
 2528' FNL & 150' FWL SWNW (TOP OF PRODUCTIVE ZONE)  
 LOCATED IN SECTION 25  
 T6N, R66W, 6TH P.M.  
 2525' FNL & 460' FEL SENE (BOTTOM OF PRODUCTIVE ZONE)  
 2525' FNL & 360' FEL SENE (BOTTOM HOLE LOCATION)  
 LOCATED IN SECTION 30, T6N, R65W, 6TH P.M.  
 WELD COUNTY, COLORADO

**SRC ENERGY**  
 1675 Broadway, Suite 2600  
 Denver, Colorado 80202

**609 CONSULTING, LLC**  
 SHERIDAN OFFICE  
 1095 Saberton Avenue  
 Sheridan, Wyoming 82801  
 Phone 307-674-0609  
 LOVELAND OFFICE  
 6706 North Franklin Avenue  
 Loveland, Colorado 80538  
 Phone 970-776-4331

DRAFTED BY:	LMO	CHECKED BY:	RKF	SHEET NO:
DATE DRAFTED:	9/26/17	DATE SURVEYED:	7/7/17	<b>3</b>
REVISED:	8/9/19	FILE NAME:	17-41	3 OF 3

K:\SYNERGY RESOURCES\2017\2017\_41\_CHALK\_T6N\_R65W\_SEC\_26\PLATS\CHALK-SEELEY 7-26 PLAT.dwg, 8/9/2019 9:45:06 AM, lba