

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402172367

Date Received:
09/11/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Lorne C Prescott</u>		<u>lprescott@laramie-energy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693200185

Inspection Date: 11/21/2018 FIR Submit Date: 11/21/2018 FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC Company Number: 10433

Address: 1401 SEVENTEENTH STREET #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335404

Location Name: CC Number: 0617-24 Pad County: GARFIELD

Qtrqtr: SESW Sec: 17 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.516247 Longitude: -108.246531

FACILITY - API Number: 05-045-00 Facility ID: 335404

Facility Name: CC Number: 0617-24 Pad

Qtrqtr: SESW Sec: 17 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.516247 Longitude: -108.246531

CORRECTIVE ACTIONS:

1 CA# 120568

Corrective Action: For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser. Date: 12/21/2018

Response: CA COMPLETED Date of Completion: 12/20/2018

Operator Comment: Lock out tag out performed, line is temporarily out of service. Item will be removed when it is no longer needed for service/operations.

COGCC Decision: Approved

COGCC Representative: Comments noted in previous inspection 693200185 "2 - 8" poly flow lines open to atmosphere, West side of location" Have been satisfied. The barrier put in place will need maintenance.

2 CA# 120569

Corrective Action: For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.

Date: 12/21/2018

Response: CA COMPLETED

Date of Completion: 12/21/2018

Operator Comment: Lock out tag out performed, line is temporarily out of service. Item will be removed when it is no longer needed for service/operations.

COGCC Decision: Approved

COGCC Representative: "2 - 2" Steel flow lines behind separators" Corrective actions have been satisfied. The Tags put in place will need maintenance. They have fell off. Better best practice would be to use 3x7 stickers to mark risers out of service

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lorne C Prescott

Signed: _____

Title: Reg&Enviro Compliance

Date: 9/11/2019 7:57:20 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402172367	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files