

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2019

Submitted Date:

09/16/2019

Document Number:

679705458**FIELD INSPECTION FORM**

Loc ID 314851 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:

Operator Information:OGCC Operator Number: 200502Name of Operator: 31 OPERATINGAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Freeman, Kris	254-727-0435	kfreeman@31operating.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229756	WELL	PR	02/19/1972	GW	103-07413	GOVERNMENT 2-34	PR

General Comment:[COGCC Inspection Report Summary.](#)

On 9-19-2019 at approximately 14:30, inspector Rick Moran, conducted a routine inspection at 31 Operating well Government 2-34 in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Stormwater sediment movement from location hillside flowing across location, and towards the White River. Photos 1, 2, 3, 4, 5, 6. Complete by 10-16-2019.
- 2) Battery sign is missing. Photo 7 & 8. Complete by 10-16-2019.
- 3) Container missing contents label. Photo 9. Complete by 10-16-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705458.

LocationOverall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:	Missing contents label on container.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/16/2019

Emergency Contact Number:

Comment:	Battery sign is missing. The side of the meter building does have the nearest public road.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/16/2019

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Gas Meter Run	# 1		
Comment:	Foundation of meter bulding is partially undercut by stormwater soil removal.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Container of unknown contents.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	229756	Type:	WELL	API Number:	103-07413	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Fail	Other	Fail			
Ditches	Fail	Culverts	Pass	Material Handling And Spill Prevention	Pass	

Comment: Stormwater sediment movement from the location hillside flowing across location, and towards the White River. The inspector followed the sediment trail from the location to the culvert going under Hwy 64. The White River is located ~100 yards from Hwy 64. One of the stormwater channels goes down the edge of the lease road.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 10/16/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705459	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4938892