

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402177206

Date Received:

09/16/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 66561

Name of Operator: OXY USA INC

Address: PO BOX 27757 #110

City: HOUSTON State: TX Zip: 77227-7757

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Montgomery, Kelley</u>		<u>Kelley_Montgomery@oxy.com</u>
<u>Rapp, Veronica</u>	<u>713-985-6966</u>	<u>Veronica_rapp@oxy.com</u>
<u>Dittrich, Wade</u>	<u>575-390-2828</u>	<u>Wade_Dittrich@Oxy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901079

Inspection Date: 08/01/2019

FIR Submit Date: 08/02/2019

FIR Status: _____

Inspected Operator Information:

Company Name: OXY USA INC

Company Number: 66561

Address: PO BOX 27757 #110

City: HOUSTON State: TX Zip: 77227-7757

LOCATION - Location ID: 333348

Location Name: Sheep Mountain Unit - Drill Site 3 Number: 047683X County: HUERFANO

Qtrqtr: NENE Sec: 22 Twp: 27S Range: 70W Meridian: 6

Latitude: 37.691320 Longitude: -105.201750

FACILITY - API Number: 05-055- -00 Facility ID: 436941

Facility Name: Sheep Mountain Number: 4-23-L

Qtrqtr: NENE Sec: 22 Twp: 27S Range: 70W Meridian: 6

Latitude: 37.691320 Longitude: -105.201750

CORRECTIVE ACTIONS:

1 ☒ CA# 128907

Corrective Action: Comply with Rule 1003 f. and perform noxious weed control and eradicate introduced specie (Small burnet). Provide the seed mixture used for this location.

Date: 08/19/2019

Response: CA COMPLETED

Date of Completion: 08/20/2019

Weed treatment conducted at the 4-23 location to control and eradicate small burnet, and address other noxious

Operator Comment: weeds that were found at the location. New seed mix approved by land owner, and will be used as needed for seeding that needs to be done in and round this drill site.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 128908

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 07/12/2019

Response: CA COMPLETED

Date of Completion: 08/22/2019

Operator Comment: Installation and repair of stormwater BMPs addressed. Land owner approved seed mix will be used to stabilize areas identified around this drill site. Seeding for stabilization will take place the week of 9/16-9/20/2019.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Weed treatment conducted at the 4-23 location to control and eradicate small burnet, and address other noxious weeds that were found at the location. New seed mix approved by land owner, and will be used as needed for seeding that needs to be done in and round this drill site.
Installation and repair of stormwater BMPs addressed. Land owner approved seed mix will be used to stabilize areas identified around this drill site. Seeding for stabilization will take place the week of 9/16-9/20/2019.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Veronica Rapp

Signed: _____

Title: Biologist

Date: 9/16/2019 8:20:16 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402177206	FIR RESOLUTION SUBMITTED
402177218	Approved seed mix

Total Attach: 2 Files