

GOLDEN EAGLE 28-16 API# 05-071-07989 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 20, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901281



PHOTO 1: Wellhead photo taken on 09/20/19 at 12:19 pm. On 09/19/19 the lease operator found the wellhead packings were leaking. The well was shut in and the packings were repaired. Due to the water level in the production pit the lease operator left the well shut in. The top layer of the soil was scraped up. The soil was dry at the time of inspection.

GOLDEN EAGLE 28-16 API# 05-071-07989 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 20, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901281



PHOTO 2: Pit level 09/20/19 at 12:27pm. 2 foot freeboard is maintained by disengaging the wellhead. A water truck is in transit to location to remove 20 BBL's of water to provide additional freeboard in the pit.

GOLDEN EAGLE 28-16 API# 05-071-07989 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 23, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901281



PHOTO 3: Pit level 09/23/19 at 10:25 am after the water truck pulled 20 BBLs on Friday 09/20/19. The well remains shut in at this time.

GOLDEN EAGLE 28-16 API# 05-071-07989 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 23, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901281



PHOTO 4: There were no impacts to the soil found from the wellhead water leak.

GOLDEN EAGLE 28-16 API# 05-071-07989 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 23, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901281



PHOTO 5: The noxious weeds were cut.

GOLDEN EAGLE 28-16 API# 05-071-07989 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 23, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901281



PHOTO 6: The noxious weeds were bagged.

GOLDEN EAGLE 28-16 API# 05-071-07989 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 23, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901281



PHOTO 7: The noxious weeds were removed from location.

GOLDEN EAGLE 28-16 API# 05-071-07989 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 24, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901281



PHOTO 8: The noxious weed rosettes were treated .