

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402179925

Date Received:
09/17/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name:

Phone: () Fax: ()

Email:

Additional Operator Contact:

Contact Name	Phone	Email
Abigail Wenk	7206446997	awenk@bisonog.com
Ariana Solis	7206446997	asolis@bisonog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200608

Inspection Date: 08/16/2019 FIR Submit Date: 08/19/2019 FIR Status:

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 455519

Location Name: Boomslang Fed 8-60 Number: 14B County:

Qtrqtr: E2SE Sec: 14 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.659078 Longitude: -104.050458

FACILITY - API Number: 05-123-00 Facility ID: 455519

Facility Name: Boomslang Fed 8-60 Number: 14B

Qtrqtr: E2SE Sec: 14 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.659078 Longitude: -104.050458

CORRECTIVE ACTIONS:

1 CA# 129382

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 09/04/2019

Operator Comment: Straw wattle installation has been corrected. Wattles have been trenched and backfiled on the upslope side.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 CA# 129383

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 09/04/2019

Operator Comment: Culverts have had geotextile liner installed underneath aggregate.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Previous inspections documented insufficient armoring above and below culverts. Operator has not indicated if armoring has been installed above culverts.

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

3 CA# 129384

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 09/04/2019

Operator Comment: Sediment traps have been cleared, with a geotextile liner added under the rock aggregate. Straw wattle has been added to location to slow stormwater discharge.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ariana Solis

Signed: _____

Title: Regulatory Analyst

Date: 9/17/2019 3:45:48 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402179925	FIR RESOLUTION SUBMITTED
402179941	Corrective Action Photos

Total Attach: 2 Files