

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Tubing on ground by well head		
Corrective Action:	Comply with rule 603 f	Date:	10/26/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type			
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 208834 Type: WELL API Number: 001-06463 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment:

Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b. Form 4 Doc# 402096885 for TA status was submitted on 7-3-19 operator is 30 past status change to perform MIT. Form 6 Doc#402101532 is also submitted.

Corrective Action: **Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208.**

Date: 10/26/2019

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday September 26, 2019 at approximately 8:47AM, I, Inspector Randy Silver, Conducted an on-site inspection at: Location: Box Elder A#1 Operator: City and county of Denver API#: 05-001-06463 County: Adams While there, I observed a well site During this inspection the following possible compliance issues were observed: Unused equipment: Rule 603 f Corrective action date of 10-26-19 See photo 1 MIT: Rule 319 b Corrective action date of 10-26-19 Weather conditions: Clear location dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	09/26/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693501442	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948321