

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2019

Submitted Date:

09/30/2019

Document Number:

693501460

**FIELD INSPECTION FORM**

Loc ID 308701 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD State: CO Zip: 8111-

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name      | Phone        | Email                           | Comment                         |
|-------------------|--------------|---------------------------------|---------------------------------|
| Mack, Ronald      |              | ronaldmack@tcenergyllc.com      | <a href="#">All Inspections</a> |
| Fitzgerald, Eddie | 719-859-1394 | eddiefitzgerald@tcenergyllc.com |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 279260      | WELL | PR     | 08/11/2005  | GW         | 071-08481 | APACHE CANYON 13-6 | PR          |

**General Comment:**

**Inspected Facilities**

Facility ID: 279260 Type: WELL API Number: 071-08481 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR](#)

Corrective Action:

Date:

**COGCC Comments**

| Comment   | User    | Date       |
|---|---------|------------|
| <a href="#">Follow up inspection to Doc# 688401803 in response to FIRR #402033141. Based on photos submitted by operator, corrective actions have been completed. (photos attached to FIRR)</a> | silverr | 09/30/2019 |